

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2206709

INV Date 01/11/2022

Reference CS/EQI22010374/Kny3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SMJ 7322T

Insured Veh. SLG 46P

Claim No. DM22HO01781/JT

Policy No. DMPPHQ22-006755

Accident Date 15/10/2022

Inspection Date 19/10/2022

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

		Affiliated to Federation Internation	nale Des Experts En Automo	bile
	EQ INSURANCE C	OMPANY LTD	Ref:	CS/EQI22010374/Kny3e2
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		Date:	01/11/2022
			Code:	EQI
1.		Policy Particulars	- THIRD PARTY CLAIN	1
	Insured Veh.	SLG 46P	Veh. Inspected	SMJ 7322T
	Policy No.	DMPPHQ22-006755	Coverage (\$)	0.00
	Claim No.	DM22HO01781/JT	Excess (\$)	0.00
	Assign From	JAIME TAY	Assign Date	18/10/2022
2.		Vehicle Partic	culars & Condition	
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72006105	Colour	METALLIC PEARL WHITE
	Odometer	39662 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Condition	ons of Tyres	
		Size	Make	Balance
		Size	Wake	24.4
	R/H Front Tyre	205/50 R16	HABILEAD	9 mm
	R/H Front Tyre L/H Front Tyre			
	<u> </u>	205/50 R16	HABILEAD	9 mm
	L/H Front Tyre	205/50 R16 205/50 R16	HABILEAD HABILEAD	9 mm 9 mm
4.	L/H Front Tyre R/H Rear Tyre	205/50 R16 205/50 R16 205/50 R16 205/50 R16	HABILEAD HABILEAD HABILEAD	9 mm 9 mm 9 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/50 R16 205/50 R16 205/50 R16 205/50 R16	HABILEAD HABILEAD HABILEAD HABILEAD On of Damages	9 mm 9 mm 9 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre	205/50 R16 205/50 R16 205/50 R16 205/50 R16 Descriptio STAINED DAMAGES AT THE FRO	HABILEAD HABILEAD HABILEAD HABILEAD On of Damages	9 mm 9 mm 9 mm
4.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	205/50 R16 205/50 R16 205/50 R16 205/50 R16 Description STAINED DAMAGES AT THE FROME	HABILEAD HABILEAD HABILEAD HABILEAD On of Damages	9 mm 9 mm 9 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS	205/50 R16 205/50 R16 205/50 R16 205/50 R16 Description STAINED DAMAGES AT THE FROME	HABILEAD HABILEAD HABILEAD HABILEAD ON OF DAMAGES ONT PORTION.	9 mm 9 mm 9 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI	205/50 R16 205/50 R16 205/50 R16 205/50 R16 205/50 R16 Description STAINED DAMAGES AT THE FROM ETAILS. General	HABILEAD HABILEAD HABILEAD HABILEAD ON of Damages ONT PORTION. Information	9 mm 9 mm 9 mm 9 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date	205/50 R16 205/50 R16 205/50 R16 205/50 R16 205/50 R16 Description STAINED DAMAGES AT THE FROM ETAILS. General 15/10/2022	HABILEAD HABILEAD HABILEAD HABILEAD ON of Damages ONT PORTION. Information	9 mm 9 mm 9 mm 9 mm
	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date	205/50 R16 205/50 R16 205/50 R16 205/50 R16 205/50 R16 Description STAINED DAMAGES AT THE FROM ETAILS. General 15/10/2022 GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721	HABILEAD HABILEAD HABILEAD HABILEAD ON of Damages ONT PORTION. Information	9 mm 9 mm 9 mm 9 mm
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date Survey held at	205/50 R16 205/50 R16 205/50 R16 205/50 R16 205/50 R16 Description STAINED DAMAGES AT THE FROM ETAILS. General 15/10/2022 GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721	HABILEAD HABILEAD HABILEAD HABILEAD ON OF DAMAGES ONT PORTION. Information Inspection Date Emarks HOUT PREJUDICE" BASIS	9 mm 9 mm 9 mm 9 mm 19/10/2022
5.	L/H Front Tyre R/H Rear Tyre L/H Rear Tyre THE VEHICLE SUS DAMAGES SEE DI Accident Date Survey held at	205/50 R16 205/50 R16 205/50 R16 205/50 R16 205/50 R16 Description STAINED DAMAGES AT THE FROM ETAILS. General 15/10/2022 GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721 Recon WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W	HABILEAD HABILEAD HABILEAD HABILEAD ON OF DAMAGES ONT PORTION. Information Inspection Date Emarks HOUT PREJUDICE" BASIS	9 mm 9 mm 9 mm 9 mm 19/10/2022



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 7322T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	BUCKLED	1,050.00	1,050.00
2	REAR BUMPER SIDE RETAINER	CRACKED	244.00	244.00
2	FRONT BUMPER CORNER RETAINER	SERVICEABLE	86.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	40.00	40.00
1	REAR BUMPER INNER REINFORCEMENT	BENT	320.00	320.00
1	FRONT GRILLE	CRACKED	395.00	395.00
1	FRONT GRILLE UPPER CHROME	SERVICEABLE	365.50	-
1	FRONT GRILLE LOWER CHROME	MTG CRACKED	280.70	231.00
1	FRONT GRILLE CENTRE 'H' LOGO	NECESSARY	72.40	72.40
2	HEADLAMP	N/S MTG CRACKED / O/S SERVICEABLE	4,500.00	2,250.00
2	HEADLAMP TOP CHROME	SERVICEABLE	426.00	-
2	HEADLAMP LOWER BRACKET	O/S SERVICEABLE / N/S CRACKED	440.00	116.00
	LESS 20% DISCOUNT		-1,643.92	-943.68
			6,575.68	3,774.72
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN)	SERVICEABLE	50.00	-
			50.00	-
	<u>LABOUR</u>			
	LABOUR CHARGES FOR REMOVE /REFIT ,CUTTING/WELDING AND REPLACEMENT OF DAMAGES.		600.00	250.00
	TO PUTTY AND SPRAY PAINTING CHARGES.		600.00	220.00
	TO CHECK WIRING AND LIGHTINGS .		40.00	15.00
	TO SUPPLY AND APPLY ANTI RUST TREATMENT.	NOT NECESSARY	50.00	-
			1,290.00	485.00
	GRAND TOTAL		7,915.68	4,259.72

Report Ref No. CS/EQI22010374/Kny3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	3,400.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/EQI22010374/Kny3e2

KONG SENG CHEONG

Licensed Appraiser

SS2E22AH0008 / S & H Motor Pte Ltd ENTRY DATE & TIME: 17/10/2022 16:55 (SGT) SUBMITTED BY: Wong Kee Nyuk VERSION: 1 (17/10/2022 16:55 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT Date of Submission 17/10/2022 16:55 (SGT) Reported by Date of Accident 15/10/2022 17:28 (SGT) Exact Location of Accident Rochor Rd, Singapore Additional Location Information Rochor Road flyover Country/State of Loss Singapore **DETAILS OF OWN VEHICLE** Vehicle Registration Number SMJ7322T INSURED/POLICYHOLDER Is company? No Name Of Registered Owner Fong Jiancong NRIC No S8216253D Email Address chivaz_boyz@yahoo.com.sg Mobile Phone No (Phone) +65-94577322 Alternative Phone No VEHICLE PARTICULARS Manufacturer Honda Model Shuttle Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission Auto CC 1500 **INSURANCE COMPANY** Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMPCSNW00060062200

Fong Jiancong

S8216253D

20/06/1982

Indoor

DRIVER

NRIC No

Name of Driver

Date Of Birth

Occupation

Date Of Driving Pass 03/09/2003 Driving experience 19 YEARS AND 1 MONTH Gender Mobile Number (Phone) +65-94577322 Alt. Phone Number Email Address chivaz_boyz@yahoo.com.sg Address Blk 5 #19-05 Tanjong Pagar Plaza Address complement Postcode 081005 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name mother-in-law Gender **Female** PASSENGER 2 Name Gender Female **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? Nο If yes, against whom? CIRCUMSTANCES OF ACCIDENT refer attached report. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Reasons for not uploading a video of the accident

DETAILS OF OTHER VEHICLE PROPERTY 1

video with workshop.

Vehicle Registration Number	SLG46P
Vehicle Manufacturer	Opel
Vehicle Model	Astra
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	Moi Siew Ling
NRIC No	S6970727J
Contact Number	(Phone) +65-90406032
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

SKETCH PLAN


IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Actual Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the ladgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

- I understand, acknowledge, agree and consent that: (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers lawyers law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (b) all insurer(s) who have insured vehicles a involved in this accident and the insurers, lawyers law firms, may are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyors/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Driver's Signature of driver is not the policyholder (i) Date Policybolder's Signature / Date &

Witnessed by Reporting Centre Personnel Name as in NR/C/ID card)



escribe	Circumstance of the Accident
On	15/10/22 at 17:28pm at Recher Rel Flyever While Stopping all the way
Car	B SLG 460 rell back despite I harn her she did not and move feward herself and hit to my front bumper 1 soll when she came ofour
Stop	and hit to my front bumper, so when she came ofour
5he	claim I hit her back of her car which is not the fact
Declara We deck	ion re the foregoing particulars are true in every respect.
2	l 17/10/22 A 17/10/22
alicyholde	's Signature / Date/ & Time Driver's Signature (if onver is not the policyholder) / Date Witnessed by Reporting Certific Personnel (Name as in NRIC(ID card)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 7322T

INSPECTION

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMJ 7322T

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

