

AE/S. REC BY: Taujau

REF:

CS/EG1220/0400/Tny 3.

ASSIGNMENT

From: _____ Date: _____

Estimated cost:

☒ OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 4500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 454K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: Mr Key

Vehicle: IN / OUT

Veh No: GBL 4493Y Yr Regn: 2017 Sep.

Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Caddy c.c. 1968

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 18084 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WV1ZZZUKZH165124

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: In order / ☒ Jammed / Leaked / Burnt or

Brake: In order / ☒ Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18
R: 21

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 20/10/22

Survey held at Wong King Rmt Bk.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s, 4/c

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐

☐ : Interview (\$ _____)

☐

☐ : Tech. invs (\$ _____)

☐

☐ : Weekend (\$ _____)

☐

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL _____

Rep. Form: _____

Lum Sum / L.B. / F. _____

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMCG22012545	Date of Loss:	17/10/2022
Vehicle Reg. No.:	GBL4493Y	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOOD 1 PTE LTD		
Driver:	WEE KOK HONG		

Make/Model:	VOLKSWAGEN CADDY TDI, 2.0 D DSG WGDR SIDE (M)	Vehicle Reg. Date:	25/09/2017
Vehicle Colour:	WHITE	Chassis No:	WV1ZZZ2KZHX163124
Engine No:	DFS221256		
Odometer:	150864 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	25

Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)
-------------------	---------------------------------------

COST OF CLAIMS

	Amount
Parts	9,229.00
Miscellaneous Items	0.00
Labour	2,140.00
Paintwork Labour	1,200.00
Towing	0.00
Gross Total (S\$)	12,569.00
+ GST 7.00% (S\$)	879.83
Nett Amount (S\$)	13,448.83

This claim is handled by: HENG SEW SOW

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** (Last Synchronised: 19 Oct 2022)**Parts:** N/A VOLKSWAGEN CADDY TDI 2.0 D DSG WGDR SIDE (M) (Model not available in database)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Woon Meng Motor Pte Ltd/GBL4493Y/19/10/2022 12:39**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	ena ✓ *450.00 F
2	2		*FRONT BUMPER RETAINER	L4X 0.00	0.00	R4 dis ✓ *70.00 F
3	1		*FRONT BUMPER SPONGE	0.00	0.00	ena ✓ *40.00 F
4	1		*FRONT BUMPER REINFORCEMENT	0.00	0.00	? *400.00 F
5	1		*FRONT BUMPER SIDE LOWER GRILLE	0.00	0.00	mis ✓ *50.00 F
6	1		*TOWING COVER	0.00	0.00	de ✓ *15.00 F
7	1		*FRONT HEADLAMP RH	0.00	0.00	ena ✓ *300.00 F
8	1		*WIPER TANK	0.00	0.00	bro ✓ *80.00 F
9	1		*SPARE TANK	0.00	0.00	? *25.00 F
10	1		*FRONT FENDER RH	0.00	0.00	bt ✓ *250.00 F
11	1		*FRONT FENDER LAMP RH	0.00	0.00	? *15.00 F
12	1		*FRONT FENDER INNER GARNISH	0.00	0.00	? *50.00 F
13	1		*FRONT SUPPORT PANEL	0.00	0.00	? *620.00 F
14	1		*FRONT SUPPORT SIDE PANEL - photo	0.00	0.00	bt ✓ *30.00 F
15	1		*EMBLEM	0.00	0.00	rel ✓ *40.00 F
16	1		*FRONT BONNET	0.00	0.00	bt ✓ *1,250.00 F
17	2		*FRONT BONNET HINGE	0.00	0.00	bt ✓ *140.00 F
18	1		*FRONT BONNET LOCK	0.00	0.00	jun ? *75.00 F
19	1		*FRONT ABSORBER RH	0.00	0.00	? *200.00 F
20	1		*FRONT KNUCKLE ARM RH	0.00	0.00	bt ✓ *400.00 F
21	1		*FRONT ABSORBER STOPPER	0.00	0.00	? *35.00 F
22	1		*FRONT ABSORBER COVER	0.00	0.00	? *25.00 F
23	1		*FRONT WHEEL BEARING	0.00	0.00	bt ✓ *220.00 F
24	1		*STABILIZER BAR	0.00	0.00	? *250.00 F
25	1		*FUEL FILTER	0.00	0.00	? *60.00 F
26	1		*STEERING AIR BAG	0.00	0.00	alt ✓ *1,700.00 F
27	1		*STEERING AIR BAG ECU	0.00	0.00	alt ✓ *1,100.00 F
28	1		*DRIVER SEAT BELT	0.00	0.00	? *250.00 F
29	1		*PASSENGER SEAT BELT	0.00	0.00	? *250.00 F

F=Franchise part.

Sub Total (\$\$) 8,390.00
+ Margin on L,N Items 10.00% (\$\$) 839.00

Total Parts (\$\$) 9,229.00

Woon Meng Motor Pte Ltd/GBL4493Y/19/10/2022 12:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Estimates On Miscellaneous Items			Amount
No	Qty	Particulars	
<u>Miscellaneous Items</u>			
1	1	TYRE RIM	-
Sub Total (\$\$)			0.00

Estimates on Labour

Estimates on Labour		Lab.Type	Amount
No	Particulars		
<u>Paintwork Labour</u>			
1	TO PUTTY & SPRAY PAINTING	New 900	1,200.00
<u>Labour Items</u>			
2	TOWING FEE	New 1	60.00
3	TO REMOVE, REPLACE, REPAIR, INSTALL & WELD DAMAGED PARTS	New 800	1,100.00
4	TO R & R FRONT RADIATOR	New ?	120.00
5	TO R & R AIR CON SYSTEM. TO REFILL & TOP UP AIR CON GAS	New 7, 100	150.00
6	TO R & DRIVER SEAT BELT & PASSENGER SEAT BELT , AIRBAG.	New 180	250.00
7	TO R & R WIRING	New 30	60.00
8	TO R & R UNDERCARRIAGE	New 150	220.00
9	TO WHEEL ALIGNMENT	New 80	180.00
Gross Labour Cost (\$\$)			3,340.00

Woon Meng Motor Pte Ltd/GBL4493Y/19/10/2022 12:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Taufm 97495749
- WP' 20/10/22 @ 10am
Ex \$500, Not Authorise
taufm@lhaanta.com
10 days
P/P Resurvey before paint

[illegible]