

ASSIGNMENT

Vehicle: IN / OUT

N/S	O/S

Front

R/Bal. 18 mm

U/Bal. 4 mm

D.O.A. 29/9/22

Survey held at Cycle

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 4 mm

U/Bal. 4 mm

D.O.I. 20/10/22

The U/C / Chassis frame / 'Body Structure' affected due to collision.

TOTAL

Lump Sum / L.S. (\$)

<input type="checkbox"/>	: Site Insp	(\$
<input type="checkbox"/>	: Interview	(\$
<input type="checkbox"/>	: Tech, Invs	(\$
<input type="checkbox"/>	: Weekend	(\$



Mercedes-Benz

Steve (LKK)

20/10/22, 11:00

00-11

EXCH - ?

PIP

13

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SMP3922G

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
6222366

WIP No 60321
Reg No/Reg Date SMP3922G / 25/09/2019
Date In/Mileage / 0
Chassis No WDD2050402R4757302
Engine No 27491031651203
Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE
Colour/Trim 021 197 Obsidian B1/ 041 101 ARTICO Leat

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WC000668	Credit	17/10/2022/ 15:04	YK	395 / Yik Chan Hoe					
Z REQUEST									
Customer Request									
M BPNSUN									
POLICY NO/ACC DATE : DMPCSA00064952202 // 29/09/2022									
DRIVE IN/EXCESS : 17/10/2022 // TBA									
DATE IN/DATE SURVEY:									
BY/AUTHORIZED ON :									
A BPILAB									
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH									
A BPIRES									
RESPRAY BOOT LID, RIGHT REAR FENDER, LEFT REAR FENDER, REAR BUMPER AND REAR END, PANEL.									
A BPILAB									
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT								0.10	380.00
A BPILAB									
CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE. NETT									120.00
A BPILAB									
PLACE VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS & STRUCTURE ALIGNMENT. NETT								0.07	1000.00
A BPILAB									
REMOVE UNDERCARRIAGE FROM VEHICLE FOR THE REPLACEMENT OF COMPONENTS									2400.00
A BPILAB									
INSPECT & CONDUCT OPTICAL WHEEL ALIGNMENT. NETT									540.00
A BPILAB									
REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS, TRIMS BOARDS AND SEATS CUSHIONS FOR NEC. REPAIRS									1200.00
A BPILAB									
APPLY CAVITY WAX ON AFFECTED AREAS.									180.00
A BPILAB									120.00

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR 8500111-X

ESTIMATE FOR SMP3922G

CHINA TAIPING INSURANCE (S) PTE LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 60321
Reg No/Reg Date SMP3922G / 25/09/2019
Date In/Mileage / 0
Chassis No WDD2050402R4757302
Engine No 27491031651203
Make/Model MB/MB C 180 AVANTGARDE/AVANTGARDE
Colour/Trim 021 197 Obsidian B1/ 041 101 ARTICO Leat

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	17/10/2022/ 15:04	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
TO APPLY SEAL SEAM ON PANEL JOINTS					1.00	2522.70	00.00	2522.70
M BOOT LID					2.00	14.10	00.00	28.20
M BOOT LID RETAINER WEDGE					2.00	11.78	00.00	23.56
M BOOT LID RETAINER WEDGE					1.00	4.46	00.00	4.46
M HOLE PLUG					1.00	4.46	00.00	4.46
M HOLE PLUG					2.00	4.46	00.00	8.92
M BOOT LID W/STRIP					1.00	210.57	00.00	210.57
M BOOT LID CHROME TRIM STRIP					1.00	159.27	00.00	159.27
M BOOT LID LOCK					1.00	303.24	00.00	303.24
M BOOT LID SERVO LOCK STRIKER					1.00	490.66	00.00	490.66
M BOOT LID LOCK GEAR MOTOR					1.00	485.66	00.00	485.66
M BOOT LID C180 MODEL PLATE					1.00	120.50	00.00	120.50
M BOOT LID MERCEDES STAR					1.00	50.95	00.00	50.95
M SEALING GROMMET					3.00	2.36	00.00	7.08
M RIGHT REAR LAMP COMBINATION					1.00	746.10	00.00	746.10
M RIGHT REAR GASKET FOR LIGHT HOUSING					1.00	22.30	00.00	22.30
M REAR BUMPER					1.00	1890.59	00.00	1890.59
M REAR BUMPER LOWER					1.00	320.61	00.00	320.61
M REAR BUMPER LOWER CHROME TRIM STRIP					1.00	308.49	00.00	308.49
M RIGHT REAR BASIC MOUNTING FOR BUMPER					1.00	39.83	00.00	39.83
M RIGHT REAR BASIC MOUNTING FOR BUMPER					1.00	70.21	00.00	70.21
M REAR BASIC MOUNTING FOR BUMPER					1.00	113.94	00.00	113.94
M REAR CROSS MEMBER					1.00	772.94	00.00	772.94
M RIGHT REAR FENDER COVERING					1.00	49.23	00.00	49.23
M REAR END PANEL TRIM GARNISH					1.00	168.28	00.00	168.28
M REAR END PANEL					1.00	1655.71	00.00	1655.71
M TS TWO-COMPONENT ADHESIVE					1.00	858.76	00.00	858.76
M UNDERBODY PROTECTION WAX					1.00	116.04	00.00	116.04
M SEAM SEAL					1.00	116.07	00.00	116.07

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272

Email: chen.hoe.yik@eyelcarriage.com.sg

Nett 27,209.33
7% GST on 27209.33 1904.65

Total Payable 29,113.98

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Acknowledged by Repairer

Signature:



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	30/09/2022 16:56 (SGT)
Reported by	Both
Date of Accident	29/09/2022 15:00 (SGT)
Exact Location of Accident	1 Scotts Rd, Singapore 228208
Additional Location Information	SHAW CENTER CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP3922G
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	PANG CHEE WEE (PENG ZHIWEI)
NRIC No	SXXXX374C
Email Address	stevepangcw@gmail.com
Mobile Phone No	(Phone) +65-96193389
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	C180
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1595

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNA00064952202

DRIVER

Name of Driver	PANG CHEE WEE (PENG ZHIWEI)
NRIC No	SXXXX374C
Date Of Birth	07/10/1973
Occupation	Indoor

Valid Of Driving Pass	21/07/1999
Driving experience	23 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96193389
Alt. Phone Number	-
Email Address	stevepangcw@gmail.com
Address	35 HINDHEDE WALK #06-01
Address complement	-
Postcode	587969
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	WALL
No. Of Passenger (Including Driver)	-

SKETCH PLAN**IMPORTANT NOTICE**


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ('GIA') may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the 'Personal Information') and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the 'Insurers'), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/small packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the 'Purposes')
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan




30/9/2022

Describe Circumstance of the Accident

I was reversing car at Shaw Centre car park
and my car hit the wall and fire hose behind


Declaration

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time

30/9/2022
4.10pm

Actual Driver's Signature (if driver is not the policyholder)
/ Date & Time

 30/09/2022
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

vJun2022

2