1/20/23, 3:35 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI22010430/KVY3M4
3 Anson Road, #16-00 Springleaf Tower

Singapore 079909 **Date:** 20/01/2023

REFERENCE

Insured/Claimant: Lin Lixun Policy No: DMPCSNW00248912105

Date of Loss: 14/10/2022 Nature of Claim: OD Claim No: SNM22D207569/C01/KHONGLH

Engine No:

1ZRX535381

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX6480B

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT

(A

Reg. Date: 22/12/2015 (Man. Year: 2015) Chassis No: MR053REH104540489

Colour: Metallic Pearl White Odometer: 76400 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: S\$53,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Yokohama 7 mm Rear Left Side: Dunlop 5 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,255.00	3,938.00	1,317.00	25.06
Miscellaneous Items	415.00	288.00	127.00	30.60
Labour	772.80	747.60	25.20	3.26
Paintwork Labour	626.01	483.54	142.47	22.76
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,068.81	5,457.14	1,611.67	22.80
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	7,068.81	5,400.00	1,668.81	23.61
+ GST 7.00/7.00% (S\$)	494.82	378.00	116.82	23.61
Nett Amount (S\$)	7,563.63	5,778.00	1,785.63	23.61

INSPECTION

Date of Assignment: 20/10/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 27/10/2022 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Singapore 575722

Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jan 2023)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKX6480B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		4,025.00 F	*3,680.00 FL
<u>Sup</u>	<u>pleme</u>	entary #1				
2	1		*LH headlamp	Mtg Cracked	350.00 F	*350.00 FL
3	1		*Gearbox oil pan	Dented	120.00 F	*120.00 FL
4	1		*Gearbox oil pan gasket	Necessary	30.00 F	*30.00 FL
5	1		*Front cross member	Bent	680.00 F	*680.00 FL
6	1		*Gearbox oil	Necessary	50.00 F	*50.00 FS
F=Fra	anchise	part. S=SpcNett	. L=ListItemDisc.	_		
				Sub Total (S\$)	5,255.00	4,910.00
			- List Item Discou	nt on L Items 0.00/20.00% (S\$)	0.00	972.00
				Total Parts (S\$)	5,255.00	3,938.00

Report was unsubmitted during this print-out.

New

Gross Labour Cost (S\$)

772.80

1,398.81

747.60

1,231.14

Recommended Miscellaneous Items

Labour for panel/mechanical

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 Misc		415.00	288.00
	Sub Total (S\$)	415.00	288.00
Recommended Labour			
No Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour			
1 Labour for paintwork	New	626.01	483.54
<u>Labour Items</u>			

Report was unsubmitted during this print-out.

< END OF ESTIMATES >