

ASS. REC. BY:

REF: C121

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 853k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6-7 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SKX 6480B Yr Regn: 12, 15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

701 ALFA C.C. 1598

Colour

M.P. White A/C: Insured / Std / NI / NA

Sp. Reading

76400 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR053REH10454089

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD / AJRim or

Tyre Size:

F: YOKO 205/55 R16

R: Dun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7 mm

R/Bal.

5 mm

L/Bal.

7 mm

L/Bal.

5 mm

D.O.A.

19/10/22

D.O.I.

27/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Fr & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:

Repairer Reference: 053343

Date calculated: 19/10/2022 5:46 PM

Full Report
Registration: SKX6480B
Printed: 19/10/2022 5:46 PM

Summary Information

Claim

Location: Singapore (SG)

Work Provider:

China Taiping Insurance
(Singapore) Pte Ltd

Printed by:

SH Motor

Currency:

SGD

Claim Reference:

Date of Incident:

15/10/22

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

TOYOTA

Model:

COROLLA

Sub Model:

ALTIS CLASSIC

Model Sheet Number:

70 EW 20

Registration:

SKX6480B

VIN number:

Odometer:

Model Specs

2 ZONE AUTO AIR CON

FOG LAMPS

1.8 LTR 81 KW

PREPARE OFF VEHICLE

TWO COAT METALLIC

Not Authorised
1/1 Rmp &
Repairing After Paint
Ex TBA

6-7 days

Labour

Time Base 10 WU/h

Price = 42.00 SGD/h
WU Price SGD

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h WU Price SGD
B020	RENEW FRONT BUMPER INCLUDES: FRONT BUMPER, BOTH FOG LAMPS AND REQUIRED ATTACHED PARTS R + R NOT INCLUDED: RADIATOR GRILLE REMOVE AND REFIT	10.0	42.00
B030	R + R RADIATOR GRILLE	1.0	4.20
B020)	RENEW FRONT BUMPER REINFORCEMENT (BUMPER REMOVED) INCLUDES: FRONT BUMPER ABSORBER REMOVE AND REFIT	1.0	4.20
NO NUMBER	R + R FRONT BUMPER IMPACT DAMPER	1.0	4.20
B040	R + R HEADLAMPS (BUMPER REMOVED) INCLUDES: ADJUST HEADLAMPS	4.0	16.80
B040)	RENEW HEADLAMP ASS-WORK	2.0	8.40
B100	R + R LEFT FRONT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED	6.0	25.20

Code	Description	WU	Price SGD
B100	ATTACHED PARTS R + R R + R RIGHT FRONT WING (BUMPER AND HEADLAMP REMOVED) INCLUDES: WHEELHOUSE LINER AND REQUIRED	6.0	25.20
B060	ATTACHED PARTS R + R R + R BONNET NOT INCLUDED: INSULATION BONNET REMOVE AND REFIT.	2.0	8.40
B080	R + R BONNET HINGE/S	1.0	4.20
530111	R + R BONNET LOCK	5.0	21.00
B060	R + R ENGINE COMPARTMENT INSULATION	1.0	4.20
B131	RENEW R/FRONT PANEL CARRIER	5.0	21.00
851091)	R + R WASHER RESERVOIR	6.0	25.20
B085	R + R WIPER LINKAGE	3.0	12.60
B085	RENEW WATER BOX LOCKING PANEL	2.0	8.40
M010	R + R AIR CONDITIONING CONDENSER INCLUDES: DRAIN + REFILL AIR CONDITIONING FLUID	10.0	42.00
M010	DRAIN AIR CONDITIONING	3.0	12.60
M020	R + R RADIATOR INCLUDES: BLEED COOLING SYSTEM	5.0	21.00
420091A)	R + R L/F WHEEL/TYRE	2.0	8.40
473101A)	DETACH + REFIT FRONT BRAKE CALIPER	2.0	8.40
431151)	DETACH + REFIT LEFT FRONT SHOCK ABSORBER	2.0	8.40
431151A)	DETACH + REFIT FRONT SHOCK ABSORBER	4.0	16.80
431151)	DISS/ASS LEFT SPRING STRUT	1.0	4.20
431011)	R + R LEFT FRONT CONTROL ARM DOES NOT INCLUDE: VEHICLE ALIGNMENT	2.0	8.40
431011A)	R + R TRAILING ARM ADD/WORK	5.0	21.00
434211)	R + R L/F STEERING KNUCKLE (WHEEL REM)	4.0	16.80
434211)	RENEW LEFT FRONT STEERING KNUCKLE DOES NOT INCLUDE: VEHICLE ALIGNMENT	7.0	29.40
434021A)	R + R FRONT WHEEL HUB SUSPENSION	5.0	21.00
431401A)	R + R FRONT CONTROL ARM BALL JOINT/S	4.0	16.80
042214)	BALANCE WHEEL/S	2.0	8.40
0471	BONNET REPAIR	10.0*	42.00
0741	L/F WING REPAIR	5 10.0*	42.00
0742	R/F WING REPAIR	5 10.0*	42.00
1007	L/F PANEL SUPPORT REPAIR	10.0*	42.00
1017	FRT UPP LOCK CARRIER REPAIR	15 30.0*	126.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		18.40	184.0
Total of Labour			772.80

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	R/F PANEL SUPPORT SURFACE PAINT	4.0
	FRONT BUMPER NEW PART PAINT K1G	19.0
	BONNET REPAIR PAINTING <50%	23.0
	L/F WING REPAIR PAINTING <50%	10.0
	R/F WING REPAIR PAINTING <50%	10.0

Paint Work

SYSTEM AZT

Time Basis 10 WU/h

Code	Description - TWO COAT METALLIC	WU	Price SGD
	L/F PANEL SUPPORT SURFACE PAINT	4.0	
	FRT UPP LOCK CARRIER SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
1008	R/F PANEL SUPPORT SURFACE PAINT	1.49
0281	FRONT BUMPER NEW PART PAINT K1G	60.10
0471	BONNET REPAIR PAINTING <50%	45.87
0741	L/F WING REPAIR PAINTING <50%	11.31
0742	R/F WING REPAIR PAINTING <50%	11.31
1007	L/F PANEL SUPPORT SURFACE PAINT	1.49
1017	FRT UPP LOCK CARRIER SURFACE PAINT	3.74

Labour Cost - Paint

Factor

42.00 SGD/h

Hrs WU Price SGD

Time Paint

74.0

Preparation Main Work Metal

2.50

25.0

105.00

Preparation Comp. Work Plastic

0.80

8.0

33.60

Total

10 WU/h

10.70

107.0

449.40

Material Cost - Paint

Price SGD

New Part Painting - Plastic K1G

60.10

Repair Painting

68.49

Surface-/Blend Paint

6.72

Material-constant Metal Preparation

28.60

Material-constant Plastic

12.70

Total

176.61

Spare Parts

prices as at 2015-06-01/01

Code	Description	Part Number	Part Source	Price SGD
0251	LWR RADIATOR GRILLE	53112 02630	Original	75.00 ?
0254	R/FOG LAMP BRACKET	81481 02450	Original	85.00 ?
0281	FRONT BUMPER	52119 02955	Original	230.00 ✓
0318	R/F BUMPER BRACKET	52115 02270	Original	40.00 ✓
0340	FRT BUMPER SUPPORT	52131 02190	Original	180.00 ?
0341	FRT BUMPER ABSORBER	52611 02310	Original	65.00 ?
0410	FRONT GRILLE	53100 02670	Original	180.00 ?
0475	L/BONNET HINGE	53420 02360	Original	40.00 X
0476	R/BONNET HINGE	53410 02360	Original	40.00 X
0493	BONNET LOCK	53510 02660	Original	90.00 X
0566	RIGHT HEADLAMP ASSY	81130 02F50	Original	350.00 ✓
0638	R/F FOG LAMP	81210 0D110	Original	160.00 ?
0842	R/F WHEELHOUSE	53875 02540	Original	75.00 ?
1008	R/F PANEL SUPPORT	53202 02190	Original	280.00 ✓
1436	WASHER CONTAINER	85315 02630	Original	95.00 ✓

Code	Description	Part Number	Part Source	Price SGD
7053	L/F LWR CONTROL ARM	48069 02260	Original	120.00 ?
7065	L/F LOWER AXLE JOINT	43330 09681	Original	60.00 ?
7077	L/FR SHOCK ABSORBER	48520 8Z025	Original	180.00 ?
7081	L/F STEERING KNUCKLE	43212 02270	Original	180.00 ?
7091	L/UPP SUPP MOUNTING	48609 02200	Original	75.00 ?
7131	L/F WHEEL HUB	43502 02110	Original	75.00 ?
7201	L/FR WHEEL	42611 02670	Original	1,250.00 ✓
f: OEM Parts				0.00
n: Non-OEM Parts				3,925.00
u: Used parts				100.00
Savings				
Subtotal				
Fixed Sundry Parts Price				
Total				4,025.00

Extras

Code	Description	Price SGD
1000	LH FRONT TYRE TYRE	180.00* 80/120
1001	ECU diagnostic ECU diagnostic	150.00* ?
1002	Electrical work Electrical work	25.00* 200
1003	Wheel alignment Wheel alignment	60.00* ✓
Total Extras		415.00

Final Calculation

	SGD	SGD
Parts	3,925.00	
Fixed Sundry Parts Price	100.00	
Total Parts		4,025.00
Labour Time Base 10 WU/h		
Total 184.0 WU X 42.00 SGD/h	772.80	
Total of Labour		772.80
Total Of Extras		415.00
Paint Work Time Base 10 WU/h		
Labour Cost 107.0 WU X 42.00 SGD/h	449.40	
Material Cost	176.61	
Total Paint Including Material		626.01
Repair Cost Excludes GST		5,838.81
GST (+7.0%)		408.72
Repair Cost Included GST		6,247.53

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	17/10/2022 17:45 (SGT)
Reported by	Both
Date of Accident	14/10/2022 16:34 (SGT)
Exact Location of Accident	Duchess Rd, Singapore
Additional Location Information	Duchess Road to Bukit Timah Road Junction
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX6480B
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	Lin Lixun
NRIC No	SXXXX992D
Email Address	linlixun@gmail.com
Mobile Phone No	(Phone) +65-90040853
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Altis
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW00248912105

DRIVER

Name of Driver	Lin Lixun
NRIC No	SXXXX992D
Date Of Birth	12/06/1982
Occupation	Indoor

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

2. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages; and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


[Signature]

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC ID card)

Sketch Plan



> Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 992D

Vehicle Details

Vehicle No.: SKX6480B

Vehicle to be Exported: Yes

Intended Deregistration Date: 17 Oct 2022

Vehicle Make: TOYOTA

Vehicle Model: COROLLA ALTIS CLASSIC 1.6 CVT

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 1ZRX535381

Chassis No.: MR053REH104540489

Maximum Power Output: 90.0 kW (120 bhp)

Open Market Value: \$17,804.00

Original Registration Date: 22 Dec 2015

First Registration Date: 22 Dec 2015

Transfer Count: 0

Actual ARF Paid: \$17,804.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 21 Dec 2025

PARF Rebate Amount: \$11,572.00

Intended COE Rebate Details

COE Expiry Date: 21 Dec 2025

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$56,989.00

COE Rebate Amount: \$18,107.00

Total Rebate Amount: \$29,679.00

The information contained herein is correct as at 17 Oct 2022

OK