

CS1/SPF22010442/Cqy3

Special Instruction:

ASSIGNMENT (Office)

\$2128.40

From (Person): Hafizul Farhan of SPF Date/Time: 17/10/2022

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

Third Parties:

Claimant:

Surveyor: AIG in house surveyor

Workshop: C&amp;C

**OD/TP Re-inspection Evaluation**

To Inspect Vehicle No: SMJ 4916A Insured: QX 321X

at Workshop m/s Cycle & Carriage KIA

of 209 PANDAN GARDENS SINGAPORE 609339

Policy No: \_\_\_\_\_ Claim No: ACS/105/009/2022/061

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11/06/2022  
(Client's Record)

(Client's Record)

H.O.D. Endorsement/Date: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Date/Time: 07/12/22 Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red \$ \_\_\_\_/\_\_\_\_%; Original! \_\_\_\_ days)

Date/Time: 07/12/22 Submit Final Fig \$2128.40, 3 days (Red \$ 0/- / 0 %; Original 3 days)

[illegible]

Para(1) : Parts found not replaced	(To highlight <i>R or UB, LR, Etc</i> )
------------------------------------	---

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

Fee Charged:	
--------------	--

Date: \_\_\_\_\_

Basic &amp; Add

Transport

## Photos

Others

Total

1) Date/Time 07/12/22 File Pass to Typist

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_