



Service Request Details

Claim

S2M04AP2

Reference

CS3/ASM22010475/Gqy3

Loss Date

8 September 2022

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

9 Sep 2022 1:23:42 PM

Request Date

20 October 2022

Due Date

21 October 2023

Services

Pre-Repair Survey

Actions

Next Step

Finish the work

Complete Work



Vehicle Information

Incident Vehicle Registration #
FBR7467Y

Make
TPVD Yamaha

Model
AEROX GRD155A CVT

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics


Notes

New Message

TYPE	
SENT	20/10/22 5:59 PM

BODY

unable open document. please send on email. tks



TYPE


?

SENT20/10/22 5:17 PM

FROMHO Winnie

SUBJECT**PLEASE PROVIDE WORKSHOP DETAILS**

BODYpls refer to linked docs again. Tks



TYPE

?

SENT20/10/22 5:11 PM

FROMLKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT**PLEASE PROVIDE WORKSHOP DETAILS**

BODY**PLEASE PROVIDE WORKSHOP DETAILS**

