

**COMFORT TRANSPORTATION PTE LTD**  
**REPAIR ESTIMATE**

Vehicle No. : SHC8366G

Make : HYUNDAI

Model : IONIQ(G3)

Date: 03/10/2022

Insurance: CHINA TAIPING

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 481.10 <i>de</i>
10	FRT BUMPER CLIPS			\$ 22.00 <i>per</i>
1	FRT BUMPER SIDE BRACKET LH			\$ 28.00 <i>de</i>
1	HEADLAMP LH			\$ 2,110.30 <i>ent</i>
1	FRT BUMPER SIDE GRILLE LH			\$ 186.90 <i>ent</i>
1	FRT BUMPER MOULDING CENTRE UPPER			\$ 368.50 <i>ent</i>
1	DAY LIGHT LH			\$ 642.50 <i>XNN</i>
	<b>SUB TOTAL</b>		3196.80	\$ 3,839.30
	<b>LESS 20%</b>		2557.44	\$ 767.86
	<b>DISCOUNTED TOTAL</b>			\$ 3,071.44
				\$ - nett
	<b>Labour Charge</b>			
	PANEL BEATING			\$ 750.00 <i>350</i>
	SPRAY PAINTING CHARGE			\$ 600.00 <i>250</i>
	TUFF KOTE		630	\$ 60.00 <i>XNN</i>
	CHECK ALL LIGHTING			\$ 60.00 <i>30</i>
	<b>TOTAL LABOUR</b>			\$ 1,470.00
	<b>ESTIMATE TOTAL</b>		\$ 3187.44 2 days	\$ 4,541.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpui 2742 5747  
 WP 3/10/22 24 pm

2 days  
 p/p Resin before paint  
 Tanpui Chhantaw

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: