



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                            |                                                                              |                                                             |            |
|----------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-------------------------------------------------------------|------------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |                                                                              | Ref: CS/AGI22010486/y3<br>Date: 21/10/2022<br><br>Code: AGI |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                            |                                                                              |                                                             |            |
| Insured Veh.                                                                                                                                 | SMW 7189T                                                                    | Veh. Inspected                                              | SHD 9622E  |
| Policy No.                                                                                                                                   |                                                                              | Coverage (\$)                                               | 0.00       |
| Claim No.                                                                                                                                    | C10018036/CH                                                                 | Excess (\$)                                                 | 0.00       |
| Assign From                                                                                                                                  | SALIZAWATI HAIZAR                                                            | Assign Date                                                 | 21/10/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                |                                                                              |                                                             |            |
| Make & Model                                                                                                                                 |                                                                              | c.c                                                         | 0          |
| Engine No.                                                                                                                                   | HIDDEN                                                                       | Year of Reg.                                                |            |
| Chassis No.                                                                                                                                  |                                                                              | Colour                                                      |            |
| Odometer                                                                                                                                     | -                                                                            | Steering                                                    |            |
| Brakes                                                                                                                                       |                                                                              | Modification                                                |            |
| General                                                                                                                                      |                                                                              |                                                             |            |
| <b>3. Conditions of Tyres</b>                                                                                                                |                                                                              |                                                             |            |
|                                                                                                                                              | Size                                                                         | Make                                                        | Balance    |
| R/H Front Tyre                                                                                                                               |                                                                              |                                                             | mm         |
| L/H Front Tyre                                                                                                                               |                                                                              |                                                             | mm         |
| R/H Rear Tyre                                                                                                                                |                                                                              |                                                             | mm         |
| L/H Rear Tyre                                                                                                                                |                                                                              |                                                             | mm         |
| <b>4. Description of Damages</b>                                                                                                             |                                                                              |                                                             |            |
|                                                                                                                                              |                                                                              |                                                             |            |
| <b>5. General Information</b>                                                                                                                |                                                                              |                                                             |            |
| Accident Date                                                                                                                                | 21/10/2022                                                                   | Inspection Date                                             | 25/10/2022 |
| Survey held at                                                                                                                               | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                                                             |            |
| <b>5a. Remarks</b>                                                                                                                           |                                                                              |                                                             |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |                                                                              |                                                             |            |