

CS/WOI 22010500/Dgy<sup>3</sup>

## ASSIGNMENT

COS Dec 2026

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 18 days Res.: Yes or NoTurn Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 2635U Yr Regn: Dec, 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq c.c. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: N.A. T/Radio: Insured / Std / NI / NAEng/No: G4LEJU133551C/No: KMHG851CVKU122138

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

R/Bal: S mm

Rear

R/Bal: S mmL/Bal: S mmL/Bal: S mmD.O.A. 21/10/2022D.O.I. 26/10/2022Survey held at Berpost Sin Ming

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front y o/s Rr

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                                                           |
|-------------|------------------------------------------------------------------------------------------------|
|             | UOI. GBS 2830G                                                                                 |
|             | for balance 50 months. & calculation attached to keep in views. Dont include in survey report. |
| 14/3/23     | Final 2/3 26,000/- with 18 days of rep<br>Cred # 51710.34, 670/1                               |

Date/Time, File Pass to?

11/20/23 Final

Date/Time, File Return to?

2)

Report Format: TP

I series. Form 1 &amp; 2 &amp; 3

Days Of Repair: 18Resurvey No. of Trip: 2Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Inve (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

G1 x 25 = 1625

260 + 1625

60

80 + 80

446

2591

580

24/3/23