

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R | | | | | |
|---|---|--|-----------------|-------|-----------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | R | Ref: | CS/AGI22010530/Dny3e2 | |
| | (BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924 | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | D | ate: | 11/01/2023 | |
| | | | C | Code: | AGI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | SMP 3150S | Veh. Inspected | | SLB 3781G | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | C10018205/KY | Excess (\$) | | 0.00 | |
| | Assign From | SALIZAWATI HAIZAR | Assign Date | | 25/10/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | HONDA VEZEL | c.c | | 1496 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2016 | |
| | Chassis No. | RU11109717 | Colour | | WHITE | |
| | Odometer | 103937 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | SPORTS RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/55 R17 | GOODYEAR | | 5 mm | |
| | L/H Front Tyre | 215/55 R17 | GOODYEAR | | 5 mm | |
| | R/H Rear Tyre | 215/55 R17 | GOODYEAR | | 5 mm | |
| | L/H Rear Tyre | 215/55 R17 | GOODYEAR | | 5 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 21/10/2022 | Inspection Date | | 26/10/2022 | |
| | Survey held at JWG INTERNATIONAL PTE LTD | | | | | |
| | | 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047 | | | | |
| 5a. | 5a. Remarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | Estimate Days of Repair | | | | | |

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: