

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMP/1626A
Bm

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

4132k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

397i

Vehicle: IN / OUT

Date:

Person Contacted:

MA955830

Veh No:

SMP1626A

Yr Regn:

21/06/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Audi A4

c.c

1984

Colour

white

A/C:

Insured / Std / NI / NA

Sp. Reading

26677

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZF47KA067765

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

mm

Rear

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

20/10/22

D.O.I.

26/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The ~~Chassis~~ / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 17k

MYUC

Rear bumper (8W5607067D)

Rear fender (8W5609837) 4357

8/11/22 4/5 @ 9800 indented kenny (Red. 8273.75, 46%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 8/11/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

3

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

9800

8x15=120

120+120

50

50+50

43

80

613