

ASIS REC BY: Taffin

REF:

CSG / MS 22 010508 / Tcy 3

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

☒ TP / ☐ VS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 866K.

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SME 7954X Yr Regn: 2015 / Jan

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C200 c.c. 1991

Colour: white. A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 114119. T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WDD2050422 F063830

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☐ Nil / ☒ SRim / ☐ STD A/Rim or

Tyre Size: F: 235 / 35 R19

R: 22

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ UIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. _____

Survey held at Veh's Workshop

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/4/23 Finalised LS 837007; 3 days with Fric. (Red. 3405 / 39%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

S + RS \$ _____