

ASS. REQ. BY:

Steve

CC 3 / AIS 22010586 / EVC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

or \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Date / Time : Action / Instruction

MVR: 68K

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format: \_\_\_\_\_

Lump Sum / L.S. (\$) \_\_\_\_\_

Veh No: \_\_\_\_\_

S3L 1749K

Yr Regn: \_\_\_\_\_

26/1/17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Volkswagen Golf

c.c

1395

Colour: \_\_\_\_\_

Grey

A/C: \_\_\_\_\_

Insured / Std / Nil / NA

Sp. Reading \_\_\_\_\_

107515

T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

WVW 222AU 2HW 1/2087

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

R: \_\_\_\_\_

175/40R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. \_\_\_\_\_

4

mm

R/Bal. \_\_\_\_\_

11

mm

L/Bal. \_\_\_\_\_

4

mm

L/Bal. \_\_\_\_\_

4

mm

D.O.A. \_\_\_\_\_

21/10/22

D.O.I. \_\_\_\_\_

26/10/22

Survey held at \_\_\_\_\_

Volkswagen

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: \_\_\_\_\_

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

3 x R.S. \$1

Prices

Others

TOTAL

## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

1/3

Company  
ALLIANZ  
INSURANCE SINGAPORE PTE. LTD.  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897

Customer Details:  
Ms.  
NG  
SAN SAN  
267 TAMPINES STREET 21  
#11-17  
Singapore 520267

Document no.  
Document date 25-10-2022  
Customer no. 5211052769  
Customer GST-ID 201903913C  
Dealer 30001  
Job order number 2022031069/ 1  
Job order date 25-10-2022  
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SJL1749K	5G13HZ	26-01-2017	WVWZZZAUZH121987	Golf 1.4 CLBM 92 TSI D7F	105,315

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR				#1	200.00	214.00
9801B005	B&P DIAGNOSIS AND PROGRAMMING				#1	360.00	385.20
9801B001	R&R FRT SEAT BELT				#1	560.00	599.20
5G4857705N RAA	Three-Point Automatic Sea SEAT BELT LH	1	pcs.	1,054.64	28.00% #1	759.34	812.49
5G4857706N RAA	Three-Point Automatic Sea SEAT BELT RH	1	pcs.	1,054.64	28.00% #1	759.34	812.49
WHT003682	Bolt With Polygon Socket	2	pcs.	7.21	28.00% #1	10.38	11.11
N 98924301	Socket Hd. Screw With Pol	2	pcs.	7.34	28.00% #1	10.57	11.31
N 98926001	Socket Hd. Screw With Pol	2	pcs.	6.63	28.00% #1	9.55	10.22
8V0857819 (phsh)	Seat Belt Height Adjuster	2	pcs.	124.00	28.00% #1	178.56	191.06
N 10572403	Bolt	2	pcs.	4.35	28.00% #1	6.26	6.70
5G6827025AA	Rear Trunk Lid	1	pcs.	2,550.09	28.00% #1	1,836.06	1,964.58
D 169300M2	1k Window Adhesive	2	pcs.	51.44	28.00% #1	74.07	79.25
D 00940104	All Purpose Cleaner	1	pcs.	102.88	28.00% #1	74.07	79.25
D 00920002	Primer	1	pcs.	30.27	28.00% #1	21.79	23.32
D 181802M1	Activator	1	pcs.	26.27	28.00% #1	18.91	20.23
D 00950025	Applicator	2	pcs.	11.16	28.00% #1	16.07	17.19
5G6827505B 9B9	Hood Latch Satin Black	1	pcs.	266.89	28.00% #1	192.16	205.61
5G6827705E	BOOT LID LOCK						
	Gasket	1	pcs.	299.42	28.00% #1	215.58	230.67
5G0827469F FOD	BOOT LID WETHERSTRIP						
	Oper.Mechan.With Micro Sw	1	pcs.	2,107.78	28.00% #1	1,517.60	1,623.83
510827861A	Water Drain Hose	1	pcs.	9.54	28.00% #1	6.87	7.35
5G6867605E 82V	Trim Panel For Hatch Gate	1	pcs.	188.91	28.00% #1	136.02	145.54
5G0853687 2ZZ	BOOT LID TRIM COVER						
	Inscription Bright Chrome	1	pcs.	89.77	28.00% #1	64.63	69.15
5G0853675AT2ZZ	NAME PLATE - GOLF						
	Inscription Bright Chrome	1	pcs.	81.11	28.00% #1	58.40	62.49
5G0945087B (phsh)	NAME PLATE - 230 TSI						
	Additional Brake Light Wi	1	pcs.	183.08	28.00% #1	131.82	141.05
5G0945093AD	3RD BRAKELIGHT						
	Taillight	1	pcs.	317.12	28.00% #1	228.33	244.31
5G0945094AD	LHS TAILLIGHT INNER						
	Taillight With Rear Fog L	1	pcs.	317.12	28.00% #1	228.33	244.31
	RHS TAILLIGHT INNER						
5G6807417APGRU	Cover For Bumper Primed	1	pcs.	1,417.50	28.00% #1	1,020.60	1,092.04
5G0988492 GRU	1 Set Sensor Brackets Pri	1	pcs.	25.72	28.00% #1	18.52	19.82
5G0919491	Sensor Bracket	2	pcs.	16.92	28.00% #1	24.36	26.07
5G0919491A	Sensor Bracket	1	pcs.	16.92	28.00% #1	12.18	13.03
5G0919492A	Sensor Bracket	1	pcs.	16.92	28.00% #1	12.18	13.03
5Q0919275B GRU	Sensor Primed	2	pcs.	190.18	28.00% #1	273.86	293.03
5Q0919133 9B9	Seal Ring Satin Black	2	pcs.	1.46	28.00% #1	2.10	2.25
D 180KU2A1	2k-Plastic Adhesive	1	pcs.	85.94	28.00% #1	61.88	66.21



## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page

2/3

Company  
ALLIANZ  
INSURANCE SINGAPORE PTE. LTD.  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897

Customer Details:  
Ms.  
NG  
SAN SAN  
267 TAMPINES STREET 21  
#11-17  
Singapore 520267

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

25-10-2022  
5211052769  
201903913C  
30001  
2022031069/ 1  
25-10-2022  
SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SJL1749K	5G13HZ	26-01-2017	VWVZZZAUZH121987	Golf 1.4 CLBM 92 TSI D7F	105,315

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
D 822150A1	Bonding Agent For Plastic	1	pcs.	68.85	28.00% #1	49.57	53.04
5G6807568D 9B9	Rear Diffuser Satin Black	1	pcs.	361.39	28.00% #1	260.20	278.41
WHT005263	Rivet	4	pcs.	1.32	28.00% #1	3.80	4.07
5G0807305D	Bumper REINFORCEMENT	1	pcs.	750.84	28.00% #1	540.60	578.44
5G6807863C	Attachment Strip BUMPER CTR BRACKET	1	pcs.	73.18	28.00% #1	52.69	56.38
5G6807393A	Guide Piece LHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	28.00% #1	31.20	33.38
5G6807394A	Guide Piece RHR BUMPER BRACKET (UPPER)	1	pcs.	43.33	28.00% #1	31.20	33.38
5G6807393	Guide Piece LHR BUMPER BRACKET (SIDE)	1	pcs.	43.33	28.00% #1	31.20	33.38
5G6807394	Guide Piece RHR BUMPER BRACKET (SIDE)	1	pcs.	43.33	28.00% #1	31.20	33.38
1K8943021	License Plate Light	2	pcs.	44.37	28.00% #1	63.89	68.36
8K0973702	Flat Contact Housing With NAMBER PLATE LIGHT WIRE HOUSING	2	pcs.	12.39	28.00% #1	17.84	19.09
5G0945105	Reflector LH	1	pcs.	81.02	28.00% #1	58.33	62.41
5G0945106	Reflector RH	1	pcs.	81.02	28.00% #1	58.33	62.41
5G6813301D	Rear Apron REAR END PANEL INNER	1	pcs.	827.48	28.00% #1	595.79	637.50
5G6807126B	Bracket For Bumper	1	pcs.	14.74	28.00% #1	10.61	11.35
5G6813309	End Plate END PANEL OUTER	1	pcs.	212.15	28.00% #1	152.75	163.44
D 007500A2	Zinc Spray	1	pcs.	72.86	28.00% #1	52.46	56.13
D 180003M2	2k-Body Adhesive	1	pcs.	469.52	28.00% #1	338.05	361.71
D 476KD1M2	Sealant Can Be Sprayed	1	pcs.	66.78	28.00% #1	48.08	51.45
WHT005560	Speed Nut	5	pcs.	1.80	28.00% #1	6.48	6.93
N 91017602	Weld Stud	8	pcs.	1.14	28.00% #1	6.57	7.03
5G6863459K 82V	Cover For Lock Carrier Ti END PANEL TRIM COVER	1	pcs.	141.51	28.00% #1	101.89	109.02
5G6858855F CA9	Cargo Platform Black SPARE WHEEL COVER	1	pcs.	443.33	28.00% #1	319.20	341.54
5G6858831 82V	Mounting Titanium Black SPARE WHEEL COVER BRACKET LH	1	pcs.	59.88	28.00% #1	43.11	46.13
5G6858832 82V	Mounting Titanium Black SPARE WHEEL COVER BRACKET RH	1	pcs.	59.88	28.00% #1	43.11	46.13
1K0803899D	Bolt For Spare Wheel Moun	1	pcs.	24.34	28.00% #1	17.52	18.75
5Q0825701E	Heat Shield For Exhaust M	1	pcs.	164.55	28.00% #1	118.48	126.77
	LABOUR	8.5	hrs	560.00	1960	4,480.00	4,793.60
	SPRAY PAINT	5	hrs	530.00	2650	4,240.00	4,536.80
	R&R REAR W/SCREEN	1	hrs	560.00	560.00	560.00	599.20
	TRANSFER BOOT LID MECHANISM	1	hrs	560.00	560.00	560.00	599.20
	R&R REAR LUGGAGE TRIM	1	hrs	560.00	560.00	560.00	599.20

\* end part order + 4 days

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page 3/3

Company  
ALLIANZ  
INSURANCE SINGAPORE PTE. LTD.  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897

Customer Details:  
Ms.  
NG  
SAN SAN  
267 TAMPINES STREET 21  
#11-17  
Singapore 520267

Document no.  
Document date 25-10-2022  
Customer no. 5211052769  
Customer GST-ID 201903913C  
Dealer 30001  
Job order number 2022031069/ 1  
Job order date 25-10-2022  
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SJL1749K	5G13HZ	26-01-2017	VWVZZZAUZHW121987	Golf 1.4 CLBM 92 TSI D7F	105,315

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	R&R REAR EXHAUST PIPE	1	pcs.	560.00	#1	560.00	599.20
	REAR WATER LEAK TEST	1	pcs.	100.00	#1	100.00	107.00
	RAER NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	ALLIANZ OD/RECOVERY						
	DOA: 22/10/2022						
	EXCESS:						
	SURVEY BY:						

Quotation valid till 01-11-2022

Tax Code	Labour	Material	Material Discount	GST %	GST	Total Discount	Total amount excl. GST	Total amount incl. GST
#1	1,120.00	22,204.54	4,302.93	7%	1,632.72	4,302.93	23,324.54	24,957.26
Total	1,120.00	22,204.54	4,302.93		1,632.72	4,302.93	23,324.54	24,957.26

Stem CLKK)  
26/10/22, 1.90pm

90-LI AL  
Excess ?

P/P

M. B. L.

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

8 days (not incl end pt 4 days)

All invoices are denominated in SGD, unless otherwise stated.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	22/10/2022 17:53 (SGT)
Reported by	Both
Date of Accident	22/10/2022 12:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	KEPPEL ROAD TOWARDS CANTOMENT LINK TRAFFIC JUNCTION
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL1749K
-----------------------------	----------

#### INSURED POLICYHOLDER

Is company?	No
Name Of Registered Owner	NG SAN SAN
NRIC No	S7804822J
Email Address	TRACY_NSS@YAHOO.COM.SG
Mobile Phone No	(Phone) +65-81268063
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Volkswagen
Model	Golf
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1400

#### INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2000706520

#### DRIVER

Name of Driver	NG SAN SAN
NRIC No	S7804822J
Date Of Birth	18/02/1978

Occupation	Indoor
Date Of Driving Pass	03/02/2006
Driving experience	16 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-81268063
Alt. Phone Number	-
Email Address	TRACY_NSS@YAHOO.COM.SG
Address	BLK 267 TAMPINES ST 21
Address complement	#11-17
Postcode	520267
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO THE SKETCH PLAN AND ACCIDENT STATEMENT.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGD8866L
Vehicle Manufacturer	BMW
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	ONG TONG

NRIC No	S7004849C
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person	NG SAN SAN
Gender	Female
Phone No	(Phone) +65-81268063
Address	BLK 267 TAMPINES ST 21
Address Complement	#11-17
Post Code	520267
Approximate Age Years Old	-
Injuries Sustained	CHEST PAIN ( UNDER INVESTIGATING)
Injured person in which vehicle?	SJL1749K
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

# SKETCH PLAN

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


*4:31 PM*  
*27 Oct 2022*

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## Sketch Plan






**Describe Circumstances of the Accident**


I stopped my car due to red light at the traffic light junction of Keppel Road towards Tans & Cantonment Link. suddenly a car BMW, hit onto the back of my car.

**Declaration**

We declare the foregoing particulars are true in every respect.

 4:31pm  
22 Oct 2022  
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre's Personnel



# SINGAPORE POLICE FORCE



T/20221023/7013

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20221023/7013

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 23/10/2022 13:28		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: NG SAN SAN		Address: 267 TAMPINES STREET 21 #11-17 SINGAPORE 520267			
ID Type / ID No.: NRIC NO / S7804822J		Contact No.: Home/Office:		Mobile: 81268063	
Nationality: SINGAPORE CITIZEN		Email: TRACY33NG@GMAIL.COM			
Sex: Female	Age: 44	Date of Birth: 18/02/1978	Type of Informant: Driver		
Race: Chinese		Language: English		Institution / School Name:	
Occupation:		Driving Licence Information: Class: 3		Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/10/2022 12:50	Type of Location: X-Junction
Location:  CANTONMENT LINK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Conditio	No of
SGD8866L	Car	BMW		Grey		0
SJL1749K	Car	VOLKSWAGO N	GOLF 1.4 TSI AT 5G13HZ HID SR	Grey		0





**SINGAPORE  
POLICE FORCE**



T/20221023/7013

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20221023/7013

**CONTINUATION OF REPORT**

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJL1749K	ALLIANZ INSURANCE SINGAPORE PTE. LTD.	SP2000706520	26/01/2022	25/01/2023

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	NG SAN SAN	ID No.	S7804822J
Related Vehicle	SJL1749K (Car)	Contact No.	81268063
Hospital/Clinic	MOUNT ELIZABETH NOVENA HOSPITAL	Class of Driving Licence & Expiry	Class: 3 Date of Expiry: NIL
Date	22/10/2022	Date	22/10/2022
No. of Days granted Medical Leave	03	Degree of	Slight

**Brief Details.**

I stopped my car SJL1749K at the red light of the cross junction of traffic light along Keppel road (towards TUAS) and Cantonment Link. My car was stationary waiting for green arrow for right turn into Cantonment link. Suddenly, a grey BMW, SGD8866L, ram into my rear.





**SINGAPORE  
POLICE FORCE**



T/20221023/7013

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20221023/7013

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
TAY CHUN KEEN  
Contact No.: 65476436

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:  
23/10/2022 13:28

Classification Of Case:

NP168