S. RECBY: Tought - REF. US LPC 22	2610587/TVC
7	STONMENT
om: Date:	Veh No: GBC 9608 Z- Yr Regn: 2014 Movel.
stimatedfost.	Type: M.Car / M.Cycle / Bus / Tan / Lorry / Taxi / Prime Mover /
DITP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
InspecVehicle No:	Make: Renart Kengoo. c.c 1598
Workship m/s	Colour Rung L A/C: Insured / Std / NI / NA
f	Sp.Reading 156231 T/Radio; Insured / Std / NI / NA
nsured:	Fno/No:
olicy No.	C/No: VF(FW/4BA562* 48383
Claims Ne	Gen. Cond; Good / Fair / Poor / Burnt
Sum Insted: Excess: 93000	Steering: Inofder / Jammed / Leaked / Burnt or
(Client'sRecord)	Brake: Inorder / Jammed / Leaked / Burnt or
viake of Veh:	Modi: (Nip/S/Rim / STD A/Rim or
	Tyre Size: F: (95/65/45
(Policy Condition)	R: 15
Remark: The veh had commenced its N/S O/S	
repair at the fime of inspection.	TOYOTYOKO DT Lingling.
Bal. or Market Value: 416 K.	Froni Rear
IDAC Accident Roort Consistent? : Yes or No	R/Bal, 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	UBaL 6⋅ mm . UBaL 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. D.O.L. 26/00/22
Lum Sum: % 3 Val.: Yes or No	Survey held at Falcon AL
CA / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / O Rooftop or
,Vehicle: IN / C	OUT
Date: Person Contacted: Andy	The U/C / Chassis frame / Body Structure affected due to collision.
Date/Time Action/Instruction New York Company	
Repealer limit 98K.	
Date/Time, File Pass 10? Preli Report	
- I sin report	Days Of Repair:
1) Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
	Transportation:
Add	Fee: Site Insp (\$) _ S+RS_SI
Jacob Bernett	: 'n'terview (\$) Photos
Reput Former: Lunar Sum / I.B. : //p	Tech. invs (%) Others
是在4.782、夏·斯尔特 / 李·萨··································	Weekeno (K

1

Co. Reg. No.: 199501140D GST Reg. No.: 199501140D



FALCON-AIR

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE 199555 ATTENTION: GERALD POH

Attention: Motor Claim Department

Contact: 62507388 Fax No.: 62962706

Estimate: ES012492

Date: 26/10/2022

Vehicle Num.: GBC 9608Z

Make/Model: RENAULT KANGOO II EXPRESS-2013/2

Chassis/Eng#: VF1FW1UBA50248383

Accident Date: 21/10/2022

Claim No.:

Reference: O/D

Policy No.: Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
		PARTS PURCHASED :		
1.	1 PC	REAR BUMPER		380.00 aug
2.	1 PC	TAILLAMP LOWER GARNISH		250.00 and
3.	1 PC	RH REAR WHEEL HUB CAP		120.00
4.	1 PC	RH SLIDING DOOR		750.00
5.	1 PC	RH SLIDING DOOR PROTECTOR PAD		115.00 at
6.	1 PC	RH SLIDING DOOR OUTER HANDLE		135.00art
7.	1 PC	RH FRONT DOOR		1,800.00
8.	1 PC	RH FRONT DOOR PILLAR A		1,300.00 <u>?</u>
9.	1 PC	RH FRONT DOOR HINGE (TOP)		200.00?
10.	1 PC	RH FRONT DOOR HINGE (BOTTOM)		200.00 /
11.	1 PC	RH FRONT DOOR PROTECTOR PAD		130.00 cm
12.	1 PC	RH FRONT DOOR OUTER HANDLE		140.000
13.	1 PC	RH FRONT DOOR INNER LOCK		430.007
14.	1 PC	RH FRONT DOOR GLASS		380.00 bus
15.	1PC	RH FRONT DOOR GLASS OUTER MOULDING		280.00 %
16.	1 PC	RH FRONT DOOR GLASS CHANNEL RUBBER		280.00 34
17.	1 PC	RH SIDE MIRROR BASE		380.00
18.	1 PC	RH SIDE MIRROR GLASS		130.00 hu
19. 20.	1 PC	RH SIDE MIRROR BACK COVER		170.00 po
21.	1 PC 1 PC	RH FRONT FENDER		345.00
22.	5 15 Centil	RH FRONT FENDER LINDERSHIELD		160.00 and
22.	1 PC	RH FRONT FENDER UNDERSHIELD		180.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D GST Reg. No.: 199501140D



FALCON-AIR

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE 199555 ATTENTION: GERALD POH

Attention: Motor Claim Department

Contact: 62507388 Fax No.: 62962706

Estimate: ES012492

Date: 26/10/2022

Vehicle Num.: GBC 9608Z
Make/Model: RENAULT KANGOO II EXPRESS-2013/2
Chassis/Eng#: VF1FW1UBA50248383
Accident Date: 21/10/2022

Claim No.: Reference: O/D

Policy No.: Z22VC05010613

S/N	Quantity	Particular	Unit Price Amount S\$
35.	1 PC 1 PC 1 PC 1 PC 1 PC 1 PC 1 PC 1 PC	RH FRONT STEEL RIM RH FRONT WHEEL HUB CAP RH FRONT SHOCK ABSORBER RH FRONT SHOCK ABSORBER TOP MOUNTING RH FRONT SHOCK ABSORBER TOP BEARING RH FRONT SHOCK ABSORBER COVER RH FRONT KNUCKLE ARM RH FRONT WHEEL BEARING HUB RH FRONT LOWER ARM RH FRONT STABILIZER BAR RH FRONT STABILIZER BAR RH FRONT STABILIZER BAR LINK RH HEADLAMP RADIATOR SUPPORT PANEL RH REAR FENDER	240.00 ht = 120.00 cm = 155.00 ? 70.00 ? 65.00 ? 750.00 ? 130.00 ? 200.00 ? 380.00 ? 155.00 ? 550.00 cm = 2,000.00 & 2
		Total Parts Purchased S\$: 15.00% Of The Above Parts S\$: Based On Cost Plus S\$:	13,680.00 2,052.00 15,732.00
2. 1	I PC I PC I PC	SPECIAL NETT ITEMS: RH FRONT DOOR COMPANY NAME STICKER RH FRONT TYRE SEALANT	50.00 at - 140.00 ? 40.45.00 re

CONTINUE / ...

FALCON - AIR AUTO SERVICES PTE LTD (a subsidiary of Falcon-Air Holdings Pte Ltd)

FALCON-AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D GST Reg. No.: 199501140D

LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THEAQNCOURSE 49A555R ATTENTION: GERALD POH

Attention: Motor Claim Department

Contact: 62507388 Fax No.: 62962706

Estimate: ES012492

Date: 26/10/2022

Vehicle Num.: GBC 9608Z Make/Model: RENAULT KANGOO II EXPRESS-2013/2 Chassis/Eng#: VF1FW1UBA50248383

Accident Date: 21/10/2022

Claim No.: Reference: O/D

Policy No.: Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
				60
	10 PCS 1 SET	RH FRONT FENDER CLIP ASSORTED CLIPS	8.00	80.00 30 m
•	, oct	AGGORTED GEIFS		
		Special Nett Total S\$:		395.00
		LABOUR:		80
		TO REMOVE/REFIT RH SLIDING DOOR GLASS		100.00
		TO CHECK WIRING AND RE-FOCUS HEADLAMP		0U.UU
		COMPUTERISE WHEEL ALIGNMENT TO TRANSFER FRONT DOOR MECHANISM		120.00 8 0 100.00 5 3
		TO TRANSFER REAR DOOR MECHANISM		100.00
		TO TRANSFER TYRE TO NEW RIM AND BALANCING		50.00 30
		TO VACUUM, RE-OIL AND RE-GAS AIR CON		120.00
		TO REMOVE/REFIX TRIM BOARD, CARPETS, GARNISHES TO		
		FACILITATE REPAIRS		280.00 /20 400.00 20
		TO REMOVE/REPLACE UNDERCARRIAGE PARTS		400 00 20
		TO CUT OUT/RE-WELD RH REAR FENDER RH FRONT DOOR PILLAR		tho
		REPAIR RH WINDSCREEN PILLAR, RH ROCKER PANEL CENTRE		
		PANEL INCLUDING REPLACEMENT OF PARTS		1,800.00
		TO SPRAY PAINT RH FRONT FENDER, RH FRONT DOOR PILLAR,		1,500.00 / 126
		RH FRONT DOOR, RH SLIDING DOOR, RH REAR FENDER RH		
		ROCKER PANEL, RH CENTRE PANEL, RH WINDSCREEN PILLAR		2,000.00 /5
		Labour Total S\$:		5,120.00
				3,120.00

E. & O.E.

Total S\$:

21,247.00

========

for FALCON AIR AUTO SERVICES PTE LTD

The quatation was prepared from visual inspection. Futher materials and labour charges may be required when repair commences. We will advise you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Taufier 97495749 Ex. \$3000 26/w/22 W.7 Anthouse C370pm

FALCON - AIR AUTO SERVICES PTE LTD (a subsidiary of Falcon-Air Holdings Pte Ltd)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID: Vehicle Details	109E
Vehicle No.:	GBC9608Z
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2022
Vehicle Make:	RENAULT
Vehicle Model:	KANGOO II EXPRESS 1.6L AT ABS AB 2WD 6DR
Primary Colour:	Brown
Manufacturing Year:	2013
Engine No.:	K4MZ835D004760
Chassis No.:	VF1FW1UBA50248383
Maximum Power Output:	
Open Market Value:	\$17,848.00
Original Registration Date:	17 Mar 2014
First Registration Date:	17 Mar 2014
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$893.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	16 Mar 2024
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$56,302.00
COE Rebate Amount:	\$7,797.00
Total Rebate Amount:	\$7,797.00

The information contained herein is correct as at 26 Oct 2022

SINGAPORE ACCIDENT STATEMENT

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

4. The Issue and acceptance of this Form by insurance companies is not all admission of policy frauntly on the part of the insurance assignment to the Police for investigation.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT Date of Submission 22/10/2022 12:40 (SGT) Reported by Date of Accident 21/10/2022 17:47 (SGT) Exact Location of Accident Singapore Additional Location Information SUNGEI KADUT ST 2 TO ST 1 Country/State of Loss Singapore DETAILS OF OWN VEHICLES Vehicle Registration Number GBC9608Z INSURED/POLICYHOLDER Is company? Name Of Registered Owner MALFORD CERAMICS PTE LTD Company Reg No 1XXXXX109E Email Address FRANCIS@MALFORD.COM.SG Mobile Phone No (Phone) +65-96382766 Alternative Phone No VEHICLE PARTICULARS Manufacturer Renault Model Kangoo Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to your vehicle? Yes Vehicle Category Goods vehicle Transmission Manual CC 1600 INSURANCE COMPANY Name of Insurance Company Lonpac Insurance Bhd Policy Number / Cover Note Number Z22VC05010613 DRIVER Name of Driver AMIN MD AL Work Permit No

GXXXX384R

15/10/1998

Outdoor

Date Of Birth

Occupation

Date Of Driving Pass Driving experience	13/05/2022 5 MONTHS
Gender Mobile Number	Male (Phono) +65 80241613
Alt. Phone Number	(Phone) +65-89241613
Email Address	FRANCIS@MALFORD.COM.SG
Address	NA
Address complement	A transfer of the control of the con
Postcode Is the driver the policyholder?	
If No, Relationship of the Driver with the Insured	No SUB CON
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	
Insurance Company of Other Vehicle Owned by Driver	
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Collision - Major/Minor Rd
Weather Conditions	Raining
Road Surface	Wet
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance? Translator's name	No
Translator's ID	
Translator's phone number	
Translator's email	
Original language used in the statement	
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	
CIRCUMSTANCES OF ACCIDENT	
REFER SKETCH PLAN	
ATTACHMENT(S)	
Are accident photos available for attachment?	Yes
Vas there any video captured by Car Camera?	No
LE DE LAILS OF OTHER!	VEHICLE PROPERTY: 1
DETAILS OF OTHER	VEHICLE PROPERTY 1
ehicle Registration Number	VEHICLE PROPERTY: 1: YQ4017R
ehicle Registration Numberehicle Manufacturer	
ehicle Registration Numberehicle Manufacturerehicle Model	
ehicle Registration Number ehicle Manufacturer ehicle Model ehicle Variant	
ehicle Registration Number ehicle Manufacturer ehicle Model ehicle Variant ehicle Colour	YQ4017R - - -
ehicle Registration Number ehicle Manufacturer ehicle Model ehicle Variant ehicle Colour ehicle Category	
ehicle Registration Number ehicle Manufacturer ehicle Model ehicle Variant ehicle Colour	YQ4017R - - -

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Onver
- Information provided must be as institutional accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy trability on the part of the insurance companies
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6 This report will be forwarded by the insurers to the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available atoresaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquines by me:
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

ALCON

Sketch Plan

Reter astachal

vJun2022

	Ŧ ħ					D B D
	21/10/22 Abode - 05.47 fm.					= Chnom 1 Nohi
	0 2					A B C
	47					401.
	?					18 J
				2 251		20
						Conse
			7			
1						
ACTION AND ACTION AND ACTION AND ACTION AND ACTION AND ACTION ACTION AND ACTION						
			-		a)	
					Sungei	
10-140-100 MINI 1			1			V. Santanian Mark at a Section
		1	15.7-52		Kadoj	
			R		13	
and the formation	and the second second second second second	Add Mercus according		1	1.12	
			7/:		4.	
ZK	tubod igene	9	1 . 1		4	and the Mark State of the Control of
				no 1		and the second s
Market			13	0		
				Cultury vicente.	hant severe en everale	CONTRACTOR OF THE PROPERTY OF
			1	1,200		
	and the state has a great or			7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	2	
		ron e	<u> </u>			
		1	- 13		51 - 55 - 55	
		(mitc.	` `			Present Control Control Control

Describe Circumstance of the Accident	
On 21/10/2022 at about 5.47pm, 1	
was travelling along sunger Kadur St 2	
intending to turn right to Snigei kadnt st 1	
there was an extremely long heavy relicelo	a sector to the
in front of my relice morning relatively slow.	
1=100 relicie & (YQ4017R) coming very fair	1
on my right à collided onto the right	n engrappanakky #
side quin rehicle.	er Bertholdty (To mpe Bether in
	1
	a. Martin and a second second

Declaration I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) Witnessed by Reporting Centre Personnel (Name as in NRIC/IO card)

vJun2022