


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SKK119 D
 at Workshop m/s Zoom
 of SKS9495R
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$65k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: days Res.: Yes or No
 Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

146D

Vehicle: IN / OUT

Date: _____ Person Contacted: 271534363

Date / Time Action / Instruction 20719k.

Veh No: SKK119D Yr Regn: 01/07/15
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA / Hatchback
 Make: Mini coopers c.c 1998
 Colour: Red A/C: Insured / Std / NI / NA
 Sp. Reading: 15364 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WMWXM720702A77171
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/40R18 R: 215/40R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 25/10/22 D.O.I. 27/10/22
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) \$ + RS. \$ SI

) Photos

) Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	146D
Vehicle Details	
Vehicle No.:	SKK119D
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Oct 2022
Vehicle Make:	MINI
Vehicle Model:	COOPER S HATCHBACK 3DR LED DSC NAV
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	F6391137B48A20A
Chassis No.:	WMWXM720702A77171
Maximum Power Output:	141.0 kW (189 bhp)
Open Market Value:	\$27,423.00
Original Registration Date:	01 Jul 2015
First Registration Date:	01 Jul 2015
Transfer Count:	2
Actual ARF Paid:	\$25,393.00 12696
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jun 2025
PARF Rebate Amount:	\$15,235.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$74,501.00
COE Rebate Amount:	\$19,128.00
Total Rebate Amount:	\$34,363.00

The information contained herein is correct as at 27 Oct 2022.

OK

