

SMR 8101R. 2016 August.

TP Chinn.  
Hui Rong

BMW 116D. 1496 cc

WBA1V72050V724584

Reer LH Fender.

Reps

1562. +

Reer LH Wheel Rim.

at

~~1200.~~ 8w/su)

Rocker Panel Outer Skirting LH.

Reps

798. +

8w/su)

Panel Beating

~~600~~ 200

Spray Painting.

~~800~~ 400.

Wiring.

~~50~~ X

680

To perform wheel alignment.

~~150~~ 80.

Wheel: 1480

L/S: 1150

02 Days.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: