

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                 |              |                        |  |
|---|--|---|-----------------|--------------|------------------------|--|
|   | HSBC LIFE (SING)   | APORE) PTE LTD                                      |                 | Ref:         | CC4/ASM22010643/Upa3q2 |  |
|   | 10 MARINA BOULI<br>#48-01 MARINA BA<br>2SINGAPORE 018  | AY FINANCIAL CENTRE TOWER                           |                 | Date:        | 04/04/2023             |  |
|   | ATTN:YVONNE  |   | 1               | Code:        | HSB                    |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |   |                 |              |                        |  |
|   | Insured Veh.   | SH 8318P  | Veh. Inspected  |              | FBQ 1462E              |  |
|   | Policy No.   | P2465679  | Coverage (\$)   |              | 0.00                   |  |
|   | Claim No.  | S2M04BTJ  | Excess (\$)     |              | 0.00                   |  |
|   | Assign From  |   | Assign Date     |              | 26/10/2022             |  |
| 2. Vehicle Particulars & Condition                                |  |   |                 |              |                        |  |
|   | Make & Model   | YAMAHA MTN155                                       | c.c             |              | 155                    |  |
|   | Engine No.   | HIDDEN  | Year of Reg.    |              | 2019                   |  |
|   | Chassis No.  | MH3RG5620K0004015                                   | Colour          |              | BLUE                   |  |
|   | Odometer   | -   | Steering        |              | IN ORDER               |  |
|   | Brakes   | IN ORDER  | Modification    |              | SPORTS RIM             |  |
|   | General  | GOOD  |                 |              |                        |  |
| 3. Conditions of Tyres  |  |   |                 |              |                        |  |
|   |  | Size  | Make            |              | Balance                |  |
|   | R/H Front Tyre   | 110/70 R17  | MAXXIS          |              | 6 mm                   |  |
|   | L/H Front Tyre   |   |                 |              | mm                     |  |
|   | R/H Rear Tyre  | 150/60 R17  | MAXXIS          |              | 6 mm                   |  |
|   | L/H Rear Tyre  |   |                 |              | mm                     |  |
| 4. Description of Damages   |  |   |                 |              |                        |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.   |   |                 |              |                        |  |
|   | DAMAGES SEE DETAILS.   |   |                 |              |                        |  |
| 5.  | General Information  |   |                 |              |                        |  |
|   | Accident Date  | 25/09/2022  | Inspection Date | <del>)</del> | 27/10/2022             |  |
|   | Survey held at   | EROFIA MOTOR TRADING PTE LTD                        |                 |              |                        |  |
|   |  | 1 KAKI BUKIT AVENUE 6<br>#02-62<br>SINGAPORE 417883 |                 |              |                        |  |
| 5a.   | Remarks  |   |                 |              |                        |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                 |              |                        |  |
| 5b.   | Estimate Days of Repair  |   |                 |              |                        |  |
|   | ESTIMATED NORI   | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days  |                 |              |                        |  |
|   |  |   |                 |              |                        |  |