



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|--------------------------|------------|
| INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | | | Ref: CS/III22010647/Kqy3 | |
| | | | Date: 27/10/2022 | |
| | | | Code: III2 | |
| 1. Policy Particulars :- OWN DAMAGE | | | | |
| | Insured Veh. | | Veh. Inspected | SMG 4727U |
| | Policy No. | D18MFL0003414_03 | Coverage (\$) | 0.00 |
| | Claim No. | | Excess (\$) | 0.00 |
| | Assign From | DERRICK TAN | Assign Date | 27/10/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | | Colour | |
| | Odometer | - | Steering | |
| | Brakes | | Modification | |
| | General | | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | | | mm |
| | L/H Front Tyre | | | mm |
| | R/H Rear Tyre | | | mm |
| | L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| | Accident Date | 11/10/2022 | Inspection Date | 28/10/2022 |
| | Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701. | | |
| 5a. Remarks | | | | |
| | A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | |

| | |
|---|--|
| INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711 | Ref: CS/III22010647/Kqy3 Date: 27/10/2022 Code: III2 |
| 1. Policy Particulars :- OWN DAMAGE | |

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|---|------------------------|----------------|
| | Insured Veh. | | Veh. Inspected | SMG 4727U |
| | Policy No. | D18MFL0003414_03 | Coverage (\$) | 0.00 |
| | Claim No. | | Excess (\$) | 0.00 |
| | Assign From | DERRICK TAN | Assign Date | 27/10/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | | Colour | |
| | Odometer | - | Steering | |
| | Brakes | | Modification | |
| | General | | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | | | mm |
| | L/H Front Tyre | | | mm |
| | R/H Rear Tyre | | | mm |
| | L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| | Accident Date | 11/10/2022 | Inspection Date | 28/10/2022 |
| | Survey held at | COMFORTDELGRO ENGINEERING PTE LTD 205 BRADDELL ROAD BLK C, 3RD FLOOR SINGAPORE 579701. | | |
| 5a. Remarks | | | | |
| | A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | |