SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/10/2022 17:16 (SGT) Reported by Driver Date of Accident 22/10/2022 08:55 (SGT) Exact Location of Accident Singapore ALONG YISHUN AVE 1 TOWARDS YISHUN AVE 8 BESIDE Additional Location Information LOWER SELETAR TIDAL GATE Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Toyota

Vehicle Registration Number GBK5911G

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner O2 AIRCON ENGINEERING PTE. LTD. Company Reg No 2XXXXX927H **Email Address** services@o2aircon.sg Mobile Phone No (Phone) +65-94461627 Alternative Phone No

VEHICLE PARTICULARS

Model Hiace Variant Exact purpose for which vehicle was being used at time of accident **Employment** Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category

Manufacturer

Commercial vehicle Transmission Manual CC 2982

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Policy Number / Cover Note Number DMCVSNA00116022202

DRIVER

Name of Driver **CHOWHAN SHREE KANAY** Passport No/FIN GXXXX451R Date Of Birth 01/03/1981

Occupation Outdoor Date Of Driving Pass 25/09/2013 Driving experience 9 YEARS AND 1 MONTH Gender Mobile Number (Phone) +65-88548036 Alt. Phone Number Email Address services@o2aircon.sg Address 157 JALAN TECK WHYE Address complement #03-123 Postcode 680157 Is the driver the policyholder? Nο If No. Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement PASSENGER 1 Name **SELVARAJ DINESH** Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? Yes Police Station Name Rochor Neighbourhood Police Centre Police Station Phone No (Phone) +65-18002949999 Alt. Police Station Phone No (Fax) +65-63918583 Police Station Address 11 Kampong Kapor Road Singapore 208678 Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLS REFER TO THE ATTACHED STATEMENT. ATTACHMENT(S)

Yes

Yes

SD CARD TAKEN BY TP

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBN9675X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Motorcycle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Gender Phone No	CHOWHAN SHREE KANAY Male (Phone) +65-88548036
Address	-
Address Complement	-
Post Code	_
Approximate Age Years Old	_
Injuries Sustained	SLIGHT
Injured person in which vehicle?	GBK5911G
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law fire allowers) may be sited outside of Singapore, for one or more of the above Purposes.

KANAY

Policyholder's Signature / Date & Time

Oriver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan

Vehicle A: CBK 5911 G

Lower Seletar

Intal gate

Yishuin Ave 1

towards

Yishuin Are 3

escribe Circumstar AS of a	pove date and time, I was driving my vehicle (GBK 59110	G)
along Yish	in the 1 towards Yishin the 8 beside Lower Seletas	
tidal gate	, I slowed down and stopped my vehicle due to	
a traffic	accident shead on the right lane. As I was	
Stationery	volucie B (FONMOTEX) coilided into the rear portion	1
of my	vehole	

Declaration

I/We declare the foregoing particulars are true in every respect.



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)


2






























3 of 3

Report No. T/20221022/2064

Police Station Of Origin: Rochor N.P.C 11 Kampong Kapor Road SINGAPORE 208678 Tel No: 1800-2949999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature of Officer Recording The Report: A / SGT 2 Lee Jia Hui	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/10/2022 15:17
Officer In Charge Of Case: TP / GIT / SI GOH WEI LI Contact No.: 65476394	Classification Of Case:

NP168