


ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: GSL 7276M  
 at Workshop m/s 2nd  
 of \_\_\_\_\_  
 Insured: SMV1069B  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: GSL 7276M Yr Regn: 09/07/20  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or CA / P2.8  
 Make: toyota hiace c.c 2754  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 46103 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GDM 2012008999  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 195/80R15  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$ 78k.  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Triangle  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 5 mm R/Bal. 5 mm  
 L/Bal. 5 mm L/Bal. 5 mm  
 D.O.A. 14/10/22 D.O.I. 27/10/22  
 Survey held at \_\_\_\_\_

CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: LTN 12856  
 Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
M/S Body  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Replok.  
4/11/22 M/S \$ 1800 informed AM long  
(Red, 5892.75, 77%)

Date/Time, File Pass to?  : Preli. Report

1) 4/11/22  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:	
Transportation:	
_____ S + RS, _____ SI	
Photos	
Others	
TOTAL	

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ 1800 )

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	25/10/2022 16:44 (SGT)
Reported by	Driver
Date of Accident	14/10/2022 10:35 (SGT)
Exact Location of Accident	Balestier Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBL7276M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SOLUPEX PTE LTD
Company Reg No	2XXXXX657R
Email Address	andreahei@sleasing.com.sg
Mobile Phone No	(Phone) +65-97668811
Alternative Phone No	-

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Hiace
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Auto
CC	2754

### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5127298127

### DRIVER

Name of Driver	THANABALAN S/O SHANMUGAM
NRIC No	SXXXXX918B
Date Of Birth	23/05/1961
Occupation	Outdoor

Date Of Driving Pass	14/01/2004
Driving experience	18 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-82398608
Alt. Phone Number	-
Email Address	THANABALANSTAVE@GMAIL.COM
Address	BLK 86 WHAMPAO DRIVE
Address complement	#16-929
Postcode	320086
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Rochor Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18002949999
Alt. Police Station Phone No	(Fax) +65-63918583
Police Station Address	11 Kampong Kapur Road Singapore 208678
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND POLICE REPORT ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMV1069B
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



Describe Circumstances of the Accident


1

Police to Police report  
7/2022 1014/2029

Declaration  
I/We declare that the information furnished is true in every respect



S. K. K. K.



Signature of Driver

Signature of Witness

Signature of Police Officer

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	657R
<b>Vehicle Details</b>	
Vehicle No.:	GBL7276M
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	1GD8483777
Chassis No.:	GDH2012008999
Maximum Power Output:	-
Open Market Value:	\$32,758.00
Original Registration Date:	09 Jul 2020
First Registration Date:	09 Jul 2020
Transfer Count:	2
Actual ARF Paid:	\$1,638.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	08 Jul 2030
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$16,704.00
COE Rebate Amount:	\$12,856.00
<b>Total Rebate Amount:</b>	<b>\$12,856.00</b>

The information contained herein is correct as at 27 Oct 2022

OK

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$68 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

**Elantra 1.6A , 100% Loan by GV CARS FINANCING**



Secured Loan by In house finance , Warranty packages and services available.  
 GV Automobile Centre StarAd

**HIN LUNG AUTO**  
 Ho Bee Group

**30 years**  
*of car sale*

**One Stop Car Hub**  
 Finance, Insurance, Workshop  
 New and Used Cars

« Back ( 1 2 3 ) Next »

Sort by Date Posted 20 results/page

56 vehicles

Any Category
Advanced Search
Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

**Search Selection**

Hiace	Any	Any	2020	Any	Any	Any	Available
-------	-----	-----	------	-----	-----	-----	-----------



**Toyota Hiace 2.8A DX** **\$84,800**

**Fuel Type:** Diesel

2020 Toyota Hiace 5 Door Auto. Well kept. Smooth engine and gearbox. Easy loan approval. 100% loan welcomed. Fast approval low re...

Think One Automobile & Trading  
 Posted: 27-Oct-2022



**Toyota Hiace 3.0M** **\$78,800**

**Fuel Type:** Diesel

Feb 2020 super popular Toyota Hiace manual 5 doors! 1 previous owner only! Tip-top condition! Free new rear wooden plank or carpet...

ABWIN (1994) Pte Ltd  
 Posted: 27-Oct-2022



**Toyota Hiace 2.8A DX** **\$88,800**

**Fuel Type:** Diesel

100% Genuine Price & Strictly No Gimmicks! New Facelift Toyota Hiace LED Model, Automatic Gear Friendly For All Users & 5 Doors Eas...

ABWIN (1994) Pte Ltd  
 Posted: 26-Oct-2022



**Toyota Hiace 3.0M** **\$81,800**

**Fuel Type:** Diesel

14,000 Km Only 5 Door Hiace. Number 1 Choice For Business Owner Like You. Well Known For Reliability And Easy To Maintain. Servicin...

ABWIN (1994) Pte Ltd  
 Posted: 26-Oct-2022



**2017 Toyota Hiace 3.0M Diesel 5 Door (For Lease)**

5 Door Toyota Hiace Diesel 3.0M (2017) For Lease! Call for more information!! 6744 0777

More info about this vehicle



**Toyota Hiace 3.0M** **\$79,800**

**Fuel Type:** Diesel

Rear Air-Con Hiace. Number 1 Choice For Business Owner Like You. Well-Known For Reliability And Easy To Maintain. Servicing, Paintwo...

ABWIN (1994) Pte Ltd  
 Posted: 26-Oct-2022



**Toyota Hiace 2.8A DX** **\$85,800**

**Fuel Type:** Diesel

Most reliable big van in the market! Low monthly start from \$1011 only! 1 owner only, pristine condition, very well taken care unit, com...

ABS Bus Pte Ltd  
 Posted: 25-Oct-2022

PREMIUM AD

**GBL7276M Toyota Hiace**

No	Qty	Parts Description		
1	1	Rear left sliding door assy	DS/But 1602	\$ 1,812.00 ✓
2	1	Rear left sliding door lock		\$ 289.00 X
3	1	Rear left sliding door railing	??	\$ 276.00 X
4	1	Rear left fender panel	R	\$ 4,800.00 X
				\$ 7,177.00
		less 25%		\$ 1,794.25
				<u>\$ 5,382.75</u>
1	1	Rear left fender panel sealant	11	\$ 80.00 X
				<u>\$ 80.00</u>
		<b>Total parts</b>		<b>\$ 5,462.75</b>

Not Authorized  
 all  
 repairs  
 27/10/22  
 2/5 @ 1800/  
 3 days  
 when phot. After repair

**GBL7276M Toyota Hiace**



1	Labour for panel beating, cut, weld, straighten accident affected area and replace accident damaged parts.	\$ 1,000.00	500
2	To putty and spray painting accident portion.	\$ 1,000.00	500
3	To check rear lighting and wiring.	\$ 11 50.00	X
4	To remove and install rear left sliding door lock.	\$ 80.00	50
5	Towing service.	\$ 11 100.00	X
<b>Total labour :</b>		<b>\$ 2,230.00</b>	

**Total parts : \$ 5,462.75**  
**Total labour : \$ 2,230.00**  
**Total repair cost : \$ 7,692.75**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: