

COMFORTDELGRO
ENGINEERING

Our Job Ref No : 305533827
Date 27.10.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : Mr NAZ
Vehicle Reg No. SHD6685T Date of Accident : 30.09.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: INCOME --- SNA9983H
2. The finalized amount shall be:
- | | |
|---|-----------------|
| (a) Spare Parts after List discount | \$0.00 |
| (b) Labour Charges | \$680.00 |
| Total for Part-By-Part Repair Cost | \$680.00 |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | 20% |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature :
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature :
Name : NAZ
Date : 28/10/2022

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 27.10.2022
Time: 16:32:41
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305533827
REGN NO : SHD6685T
MILEAGE : 0000000000
MAKE : MERCEDES BENZ
MODEL : E220CDI(E6)
DATE OF REGN : 23.03.2016
DATE/TIME IN : 21.10.2022 16:10
ACCIDENT DATE : 30.09.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

SUB-TOTAL : 0.00

JOB NATURE

0000 PB	PANEL BEATING	400.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 680.00

TOTAL : 680.00

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

Income (L/sun)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 25.10.2022

REPAIR ESTIMATE

Time: 08:19:00

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305533827
REGN NO : SHD6685T
MILEAGE : 0000000000
MAKE : MERCEDES BENZ
MODEL : E220CDI(E6)
DATE OF REGN : 23.03.2016
DATE/TIME IN : 21.10.2022 16:10
ACCIDENT DATE : 30.09.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-2282-G	REAR BUMPER ASSY	1	1,510.00	20.00	1,208.00	X R
0002 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	✓ NEC X NN
0003 09-01-0299-2005-A	REVERSE SENSOR ASSY	1 N	388.00	10.00	349.20	X SV2

SUB-TOTAL : 1,607.20

JOB NATURE

0000 PB	PANEL BEATING	500.00	400
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 L	REMOVE/REFIX reverse sensor	50.00	30

SUB-TOTAL : 850.00

TOTAL : 2,457.20

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

NAZ LKK

25/10/2022 1750 HRS

LIS

2 Days

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: