## COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE:

25.10.22

DOA 19.10.22

MODEL

Hyundai loniq

INSURANCE INCOME

VEHICLE NO. SHC34 16D

MVA: JUMANI

PART NO.	DESCRIPTION	QTY	UNIT PRICE	A	MOUNT	-0
JACO NO.	FRT BUMPER			\$	301.10	
	FRT BUMPER CLIPS	10		5	22 00	
	FRT BUMPER CENTRE MOULDING			S	368.50	5
	FRT BUMPER SIDE BRACKET RH			\$	35.00	
	HEADLAMP ASSY RH			\$	2,110.30	150
	FRT FOG LAMP GRILLE			S	93.45	?
	FRT FENDER EMBLEM			\$	26.60	? ~~
	FRT FENDER LH			S	588.80	100
	FRT WHEEL CAP			\$	346.40	1 SCR
	SUB TOTAL			\$	4,072.15 814.43	
	LESS 20%			• \$	3,257.72	
	SUB - TOTAL					NET NET
	000 101/12					
	Labour Charge PANEL BEATING			\$ \$	1_10 <del>0.00</del> 600.00	l _
- 1	SPRAY PAINT			S	50:00	
- 1	WIRING CHARGE	1		S		40
	TUFF KOTE			4	30.00	1 70
	TOTAL LABOUR			\$	1,800.00	
	ESTIMATE TOTAL			\$	5,057.72	
1		1				

NAZ LKK 25/10/2022 1730 HRS 415 3 Days CHECK ITEM PHOTOI

AFTER REPORT PHOTO)

## COMFORT DELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

_	•	-	•	_	
	Д	. 1	П	-	

25.10.22

D.O.A 19.10.22

MODEL:

Hyundai loniq

INSURANCE: INCOME

VEHICLE NO .: SHC34 16D

MVA: JUMANI

PART NO.	DESCRIPTION	OTV		JUMANI	No.	
PARI NO.	PLEONI TEN	QTY	UNIT PRICE	AMOU		
	FRT BUMPER					xR
	FRT BUMPER CLIPS	10		\$		x svc
	FRT BUMPER CENTRE MOULDING			\$	368.50	, ,
	FRT BUMPER SIDE BRACKET RH			\$	35.00	•
	HEADLAMP ASSY RH			\$ 2,	110.30	rsce
	FRT FOG LAMP GRILLE			\$	93.45	?
	FRT FENDER EMBLEM			S	26.60	?
	FRT FENDER LH			\$	588.80	100
	FRT WHEEL CAP			\$	346.40	rsur
	SUB TOTAL			\$ 4	,072.15	
	LESS 20%			\$	814.43	1
	DISCOUNTED TOTAL			\$ 3	,257.72	
						NET
						NET
						NET
	SUB - TOTAL					
	Labour Charge					
	PANEL BEATING			s 1	400.00	700
	SPRAY PAINT				1,00.00	
	WIRING CHARGE			\$	600.00	1
	TUFF KOTE			\$		+ 30
				\$	50.00	40
	TOTAL LABOUR					
	, one cabour			\$	1,800.00	
	ESTIMATE TOTAL			\$	5,057 <i>.</i> 72	2
	This is air minual estimate based on a visual hispection or d	IC BOOVE VEIN		quantum		
	prepared after the vehicle is surveyed by a motor Su	veyor appoin	ted by the insurance	e company	VIII DE	

NAZ LKK
25/10/2022 1730 HRS
LIS
3 DAYS
CHECK ITEM PHOTO:
APTER REPAR PHOTO:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed:
- Supplementary item(s) must be lesurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: Date: