



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC22010684/Nvce2

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

Date: 04-11-2022

Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 5263P	Veh. Inspected	SHD 4909L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1194194-002	Excess (\$)	0.00
Assign From		Assign Date	25/10/2022

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI IONIQ	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHC851CVLU188409	Colour	BLUE
Odometer	352381	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MOZZO	4 mm
L/H Front Tyre	195/65 R15	MOZZO	4 mm
R/H Rear Tyre	195/65 R15	MOZZO	4 mm
L/H Rear Tyre	195/65 R15	MOZZO	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND O/S REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/10/2022	Inspection Date	25/10/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------