

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI22010706/Aqy3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	05/01/2023	
			Co	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLA 7528B	Veh. Inspected		SJT 7156P	
	Policy No.	P10330456R02	Coverage (\$)		0.00	
	Claim No.	C10018259/JY	Excess (\$)		0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date		27/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA CERATO FORTE	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2009	
	Chassis No.	KNAFW411MA5125763	Colour		BLUE	
	Odometer	144222 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	MICHELIN		6 mm	
	L/H Front Tyre	215/45 R17	MICHELIN		6 mm	
	R/H Rear Tyre	215/45 R17	MICHELIN		6 mm	
	L/H Rear Tyre	215/45 R17	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	25/10/2022	Inspection Date		27/10/2022	
	Survey held at JL PERFECT AUTOWORK PTE LTD					
		8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

9 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: