


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SDQ 8822E  
at Workshop m/s CYCLE & CARRIAGE  
of 188, PANDAN LAMP  
Insured: SMR  
Policy No. \_\_\_\_\_  
Claims No. TAX/10/22/2030  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SDQ 8822E Yr Regn: 2018 / NOV  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: MERCEDES BENZ S320L c.c. 2996  
Colour: BLUE A/C: Insured / Std / Nil / NA  
Sp. Reading: 53936 T/Radio: Insured / Std / Nil / NA  
Eng/No: \_\_\_\_\_  
C/No: WDD2221622A422768  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 245/402R20  
R: \_\_\_\_\_  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or \_\_\_\_\_



(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 285K  
IDAC Accident Rpt: Consistent? : Yes or No  
GIA / PR Seen: Consistent? : Yes or No  
Est. Repairs: 3 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Front 6 mm R/Bal. 6 mm  
L/Bal. 6 mm Rear 6 mm  
D.O.A. 09/10/22 D.O.I. 31/10/22  
Survey held at CYCLE & CARRIAGE  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
REPAIR LIMIT - 163K

We will be advising our principal a cost of repair P/P \$5,713.41 /- with 03 days of repair  
(red, \$3202.69, 36%)

Date/Time, File Pass to?  : Preli. Report  
1) 27/02/23  : Final Report  
Date/Time, File Return to?

Days Of Repair: 3  
Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
S + RS, SI  
Photos  
Others

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)

Report Format : \_\_\_\_\_