

Steve


CS/CTI 220107/8/Ewy3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLV5094M Yr Regn: 29/12/17
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Nissan Sylphy c.c. 1598
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 49965 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MNTB3AB1720030395
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / SRim / STD A/Rim or
 Tyre Size: F: 15/50R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front: _____ Rear: _____
 R/Bal. 4 mm R/Bal. 4 mm
 L/Bal. 4 mm L/Bal. 4 mm
 D.O.A. 16/10/22 D.O.I. 7/11/22
 Survey held at Wah Hong
 Des. of Damages: Frt / Rear / CR / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>MK-69K</u>

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to?

2)

Repair Format: _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	024A
Vehicle Details	
Vehicle No.:	SLV5094M
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Oct 2022
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	HR16913549C
Chassis No.:	MNTBBAB17Z0030395
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,987.00
Original Registration Date:	29 Dec 2017
First Registration Date:	29 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$16,987.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Dec 2027
PARF Rebate Amount:	\$12,740.00
Intended COE Rebate Details	
COE Expiry Date:	28 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$38,200.00
COE Rebate Amount:	\$19,736.00
Total Rebate Amount:	\$32,476.00

The information contained herein is correct as at 27 Oct 2022

OK



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. SLV5094M NISSAN SYLPHY 1.6

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Side mirror assy RH / BR		388.00	
1	Side mirror cover RH / MIF		90.00	
1	Rear door RH x R		1016.00	
1	Rear door window pillar top sticker RH X		39.00	
1	Rear door window pillar side sticker RH X		39.00	
1	Rear door handle bar (long) / NT		284.00	
1	Rear door handle bar (short) / NT		52.00	
1	Rear fender RH / DD		1533.00	
1	Tail lamp RH / BR		359.00	
1	Tail lamp clips RH X		5.00	
1	Pump fuel cover / DD		94.00	
1	Front door RH (Repair refer to labour) X		0.00	
Part Items Total:			3899.00	
			-30% -1169.70	
			2729.30	
SPECIAL NETT ITEMS				
1	Rear fender RH sealant / MC		40 60.00	
1	Rear windscreen sealant / MC		40 60.00	
SN Items Total:			120.00	
Total Parts			2849.30	

Sten (LKK)

7/11/22, 12.00h

m n

L/S

My AL 4, 6 7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. SLV5094M NISSAN SYLPHY 1.6

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1200.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1000.00	700
3	To perform anti-rust treatment on affected areas	60.00	30
4	To remove and refit rear windscreen	100.00 /	
5	To remove and replace rear door RH fitting, trimmings, garnish, window glass and lock mechanism	120.00 X	80
6	To remove and refix wiring system at accident damaged area and check for all electrical proper function	90.00	30
7	To remove and refit rear seat in order to repair	100.00	50
8	To remove and refit roots lining & upholster garnish	100.00	50
9	To remove and refix rear quarter glass RH	120.00	80
Labour Total :		2890.00	
TOTAL (PARTS & LABOUR):		5739.30	