

ASS. REC. BY: Tough

REF:

OCT1 22 0725 / Tug?

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____


Insured: **XE 6423M**Policy No. **DMCVSNW00060592201**Claims No. **SNM22D207734/C02/LEEPG**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: **975K**

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SLF1850H** Yr Regn: **2009, Jan**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: **Toyota Lexus LS250** C.C. **2500**Colour: **Grey** A/C: Insured / Std / NI / NASp. Reading: **255/47** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **JTHBK262605086 763**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or _____

Brake: In order / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: **225/55 R17**R: **27**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. **6** mm R/Bal. **6** mmL/Bal. **6** mm L/Bal. **6** mmD.O.A. **28/10/2022** D.O.I. **01/11/22**Survey held at **Bifrost**Des. of Damages: **Frt** Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/5/23 Lump Sum \$12,200 confirmed by email (Red 12,299.21, 50%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 15/5/23-typist

Days Of Repair: **5**

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

____ \$ + RS. ____ \$

Photos

Others

TOTAL

Rep. Format: **Merimen**Lump Sum / H.R. (\$ **\$12,200**)Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	087Z
Vehicle Details	
Vehicle No.:	SLF1850H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD FL
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	4GR0516953
Chassis No.:	JTHBK262605086763
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$37,374.00
Original Registration Date:	14 Jan 2009
First Registration Date:	14 Jan 2009
Transfer Count:	5
Actual ARF Paid:	\$37,374.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$19,449.00
Total Rebate Amount:	\$19,449.00

The information contained herein is correct as at 28 Oct 2022

OK

Date of Accident : 28/10/22 Accident Time: 1030 (24-HR-FORMAT)

Accident Place : BK 339 Hougang Ave 7 carpark IS 250

Vehicle Reg. No (Car plate No.) : SLF1850H Vehicle Make/Model: lexus ~~LS~~

Insurance Company : ntuc Policy No. _____

Name of Registered Owner : Company Individual m auto leasing pte ltd

ID of Registered Owner : Co Reg No: _____ Owner's NRIC No: 2020170872

: Co Contact No: _____ Owner's Contact No: 90032303

DRIVER'S Name : tok Jia Jun, marcus **DRIVER'S NRIC No:** S9932097D

DRIVER'S Date of Birth : 11/10/1999 **DRIVER'S License Pass Date** 18/10/22

Relationship bet. Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee Others: _____

DRIVER'S Address : 354 hougang Ave 7 #13-701 S (530354

DRIVER'S Contact No./ Alt No. : 1) 98239161 2) _____

DRIVER'S Occupation : INDOOR OUTDOOR (eg. working inside or outside of an ofc)

Email Address : marcus.tok36@gmail.com

Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET

Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance

Number of Passengers (including Driver): 1 Name & Gender: driver

Was the accident reported to the police? YES \ NO

Was there any video Captured by car camera: YES \ NO

Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose

Any injuries, if yes (name of the injured person) driver

Other Party Driver's Particulars (if any)

Vehicle Reg No: <u>XB 6423M</u>	Vehicle Reg No: _____
Vehicle Make/Model: <u>94662402</u>	Vehicle Make/Model: _____
Name DRIVER: <u>Kesavan balaraman</u>	Name DRIVER: _____
IC No. DRIVER: <u>G7043465U</u>	IC No. DRIVER: _____
DRIVER'S Contact & add: _____	DRIVER'S Contact & add: _____

REPORT FORM EXPLAINED IN : ENGLISH / CHINESE / MALAY / TAMIL OTHERS: _____

WHO REPORTED THE ACCIDENT : OWNER / DRIVER / BOTH

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

my vehicle was stationary along blk 339
hougang Ave 7 carpark, out of sudden vehicle (b)
was reversing and hit onto my vehicle.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel

BHAGLAAX

bpe LRR

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

LKK Auto Consultancy hence notified
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is allowed
• Without Prejudice
• Illegal modification is allowed
• Elementary work must be resurveyed
• To be removed from Insurance Company
Signed by: [Signature]

Repair Estimate

Vehicle number: SLF1850H
Make & Model: Lexus IS250
Chassis number: JTHBK262605086763

Date of survey:
Name of surveyor:
Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bonnet	1	\$ 1,759.00
2	Bonnet RH hinge	1	\$ 129.00
3	Bonnet LH hinge	1	\$ 129.00
4	Bonnet lock	1	\$ 235.00
5	Bonnet insulator	1	\$ 218.00
6	Front bumper	1	\$ 987.10
7	Front bumper number plate	1	\$ 187.00
8	Front bumper RH fog lamp	1	\$ 329.40
9	Front bumper RH fog lamp cover	1	\$ 89.10
10	Front bumper RH fog lamp side cover	1	\$ 55.30
11	Front bumper LH fog lamp	1	\$ 329.40
12	Front bumper LH fog lamp cover	1	\$ 89.10
13	Front bumper LH fog lamp side cover	1	\$ 55.30
14	Front bumper RH side retainer	1	\$ 68.00
15	Front bumper LH side retainer	1	\$ 68.00
16	Front bumper reinforcement	1	\$ 478.00
17	Front bumper inner sponge	1	\$ 158.90
18	Front bumper lower grille	1	\$ 189.20
19	Front bumper towing cover	1	\$ 31.10
20	Front bumper upper rubber seal	1	\$ 165.60
21	Front grille	1	\$ 602.00
22	Front grille emblem	1	\$ 118.30
23	Front air duct	1	\$ 113.50
24	RH headlamp	1	\$ 2,188.00
25	RH headlamp lower bracket	1	\$ 141.30
26	LH headlamp	1	\$ 2,188.00
27	LH headlamp lower bracket	1	\$ 141.30
28	Front brace panel	1	\$ 92.30
29	Support panel	1	\$ 1,296.50
30	Support panel top cover	1	\$ 304.50
31	Horns	2	\$ 215.70
32	Aircon condenser	1	\$ 1,205.00
33	Radiator assy	1	\$ 1,518.00
34	Radiator fan assy	1	\$ 1,309.00
35	Front RH fender	1	\$ 970.00
36	Front RH fender splash shield	1	\$ 278.00
37	Front LH fender	1	\$ 970.00
38	Front LH fender splash shield	1	\$ 278.00
39	Aircon condenser	1	\$ 1,281.60

Air filter ana ✓

40	Radiator assy	1	\$	1,673.80	X
41	Radiator fan assy	1	\$	971.60	X
			\$	21,589.90	
			Parts less 10%	\$	2,158.99
				\$	19,430.91

No.	Special Nett Items	Qty	Amount S\$	
1	Bonnet insulator clips	1set	\$	90.00 3 one ✓
2	Bonnet sealant	1	\$	100.00 X
3	Front grille clips	1set	\$	60.00 20 inch ✓
4	Front bumper clips	1set	\$	80.00 3 one ✓
5	Support panel top cover clips	1set	\$	70.00 X
6	Front RH fender splash shield clips	1set	\$	60.00 X
7	Front LH fender splash shield clips	1set	\$	60.00 X
8	Radiator coolant	1	\$	100.00 X
9	Front number plate	1	\$	80.00 cm 40 ✓
		1	\$	278.00
		Total:	\$	978.00

No.	Labour and painting	Amount S\$	
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1,200.00	600
2	Spray painting on affected areas and panels	\$ 1,200.00	800
3	Check wiring and lighting system on affected areas	\$ 80.00	40
4	Apply rust coating chemical on affected areas and panels	\$ 80.00	30
5	Remove and replace aircon condenser and pipes to assist repair	\$ 280.00	100?
6	Remove and replace radiator assy and hoses to assist repair	\$ 280.00	100
7	Refocus and adjust headlamps assy	\$ 100.00	40
8	Diagnose and reset control unit	\$ 450.00	X

Agreed Amount: _____ (Part by Part / Lump sum)

Tanfiah 97495249 WP 01/11/22 @ 345pm
 L/S Resing after repair - To check consistency of accident
 tanfiah@lkhauto.com - To check part prices
 5 days

Working days: _____

Spare Parts:	\$	19,430.91
Special Nett:	\$	978.00
Labour:	\$	3,670.00

Total Amount:	\$	<u>24,078.91</u>
----------------------	-----------	-------------------------

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SLF1850

Make & Model: Lexus IS250

Chassis number:

Date of survey:

Name of surveyor:

Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Air filter cover	1	\$ 467.00

\$ 467.00

Parts less 10% \$ 46.70

Total \$ 420.30

No.	Special Nett Items	Qty	Amount S\$

Total: \$ -

No.	Labour and painting	Amount S\$

Total: \$ -

Agreed Amount: _____ (Part by Part / Lump sum)

Working days: _____

Spare Parts: \$ 420.30

Special Nett: \$ -

Labour: \$ -

Total Amount: \$ 420.30

Taufik 8/11/22.