SS. REC. BY: Tought AS	SIGNMENT	2029 Jen
	61 2 10 11	Yr Regn: 2009, Jen
rom: Date:		
stimated Cost;	Type: M.Car / M.Cycle / Bus / Van / Lor .Truck / Trailer or	ry I- raxi / Prime Mover /
DD TP WS I TP RES I OD RES I EVA I INV I MV		. 20:-
o Inspect Vehicle No:	Make: Toyofg lexus US25	
at Workshop m/s	Colour Grey	
of		T/Radio: Insured / Std / NI / NA
nsured:	Eng/No:	05086.763
Policy No.		02086. 103
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt	
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked /	
(Client's Record)	Brake: Inorder / Jammed / Leaked /	
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or	1
. 10-1	Tyre Size: F: 225	1571617
(Policy Condition)	R:	7
Remark: The veh had commenced its N/S C	DIS BOIDUNIEXNOVAIGYI-FSILIZA	MIC OHTSU PIR SUMI
repair at the time of inspection.	TOYO/YOKO or	
Bal. or Market Value: 975 K	Front	Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm	R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm	L/Bal. 6. mm
Est. Repairs: days Res.: Yes or No	D.O.A.	D.O.I. 01/11/22.
Lum Sum: % 3 Val.: Yes or No	Survey held at Bit for A	
CA REV REP. 24 HRS W	Des. of Damages : Frt Rear / O/S	N/S U/C Rooftop or
Vehicle: IN	/ OUT	dy Structure affected due to collisio
Date:Person Gontacted:	Ine U/C / Chassis frame / Bo	dy directare allocate are
Date / Time Action / Instruction		
	4	
. 1 .	l.	The state of the s
	• • •	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:	
	Resurvey No. of Trip:	Survey Fee:
1) : Final Report Date/Time, File Return to?		Transportation:
	dd Fee: : Site Insp (\$)_s+RS,_SI
Δ.		
) Photos
Pep Formal:	: Interview (\$) Photos

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	087Z
Vehicle Details	
Vehicle No.:	SLF1850H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS IS250 AUTO STD FL
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	4GR0516953
Chassis No.:	JTHBK262605086763
Maximum Power Output:	153.0 kW (205 bhp)
Open Market Value:	\$37,374.00
Original Registration Date:	14 Jan 2009
First Registration Date:	14 Jan 2009
Transfer Count:	5
Actual ARF Paid: Intended PARF Rebate Details	\$37,374.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jan 2029
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$31,335.00
COE Rebate Amount:	\$19,449.00
Total Rebate Amount:	\$19,449.00

The information contained herein is correct as at 28 Oct 2022

Date of Accident	: 28/10/27 Accident Time: 1030 (24-HR-FORMAT)			
Accident Place	BIKB339 Houldong Ave 7 carnerk			
Vehicle Reg. No (Car plate No.)	SLF1850H Vehicle Make/Model: Lexus 18250			
Insurance Company	: Ntuc Policy No.			
Name of Registered Owner	(Company) Individual m auto leasing Pte Ital			
ID of Registered Owner	: Co Reg No: Owner's NRIC No2020170872			
	: Co Contact No: Owner's Contact No: 90032303			
DRIVER'S Name	: tok Jia Jun, Marcus DRIVER'S NRIC No: 59932097D			
DRIVER'S Date of Birth	: 11/10/1999 DRIVER'S License Pass Date 18/10/22			
Relationship bet. Owner & Driver	: Spouse \ Parents \Children\ Sibling \ Employee \ Others:			
DRIVER'S Address	: 354 hougang Ave 7 #13-701 S (530354			
DRIVER'S Contact No./ Alt No. :1) 9823 916 2)				
DRIVER'S Occupation	: INDOOR OUTDOOR (eg. working inside or outside of an ofc)			
Email Address	: marcustok36 Degmanl. com			
Weather & Road Surface	: CLEAR & DRY \ RAINING & WET \AFTER RAIN & WET			
Reporting Type	Reporting Only Claim Other Party Claim Own Insurance			
Was the accident reported to the poli Was there any video Captured by car	Name & Gender; driver ice? YES \\NO r camera: YES \\NO being used at the time of accident: Private use \\ Work purpose jured person \(\frac{1}{2} \			
Other	Party Driver's Particulars (if any)			
Vehicle Reg No: XB 6423M	Vehicle Reg No:			
Vehicle Make\Model: 94662402	Vehicle Make\Model:			
Name DRIVER: Kesavan balara	Name DRIVER:			
IC No. DRIVER: 670434654	IC No. DRIVER:			
DRIVER'S Contact & add:				
REPORT FORM EXPLAINED IN : ENGLISH	CHINESE / MALAY / TAMIL OTHERS:			
WHO REPORTED THE ACCIDENT: OWNE				

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

R.O.C. No.


2020170872

m

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



cribe Circumstance	Vehicle	Was	5+	ationo	iry o	ilong bil	< 339
						,	vehicle (b)
						vehicle.	
					2-		

I/We declare the foregoing particulars are true in every respect.

BHGGLAAK

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLF1850H Make & Model: Lexus IS250

Chassis number:JTHBK262605086763

the Repairer of the terlowing:

To resurvey before/all it spray painting:

To display damaged pitt(s) during resurvey:

Parts prices are smiles to confirmation:
Third party survey significant in a "Without Prejudice of the mount after a list allowed on the mount after a list al

Date of survey: Name of surveyor: Contacts:

No.	Description of spare parts	Qty	A	mount S\$
1	Bonnet	1	\$	1,759.00 129.00
2	Bonnet RH hinge	1	\$	129.00
3	Bonnet LH hinge	1	\$	129.00
4	Bonnet lock	1	\$	235.00
5	Bonnet insulator	1	\$	218.00
6	Front bumper	1	\$	987.10
7	Front bumper number plate	1	\$	187.00
8	Front bumper RH fog lamp	1	\$	329.40
9	Front bumper RH fog lamp cover	1	\$	89.10
10	Front bumper RH fog lamp side cover	1	\$	55.30
11	Front bumper LH fog lamp	1	\$	329.40
12	Front bumper LH fog lamp cover	1	\$	89.10
13	Front bumper LH fog lamp side cover	1	\$	55.30
14	Front bumper RH side retainer	1	\$	68.00
15	Front bumper LH side retainer	1	\$	68.00
16	Front bumper reinforcement	1	\$	478.00
17	Front bumper inner sponge	1	\$	158.90
18	Front bumper lower grille	1	\$	189.20
19	Front bumper towing cover	1	\$	31.10
	Front bumper upper rubber seal	1	\$	165.60
	Front grille	1	\$	602.00
	Front grille emblem	1	\$	118.30
23	Front air duct	1	\$	113.50
	RH headlamp	1	\$	2,188.00
	RH headlamp lower bracket	1	\$	141.30
26	LH headlamp	1	\$	2,188.00
27	LH headlamp lower bracket	1	\$	141.30
28	Front brace panel	1	\$	92.30
29	Support panel	1	\$	1,296.50
30	Support panel top cover	1	\$	304.50
31	Horns	2	\$	215.70
32	Aircon condenser	1	\$	1,205.00
	Radiator assy	1	\$	1,518.00
	Radiator fan assy	1	\$	1,309.00
35	Front RH fender	1	\$	970.00
36	Front RH fender splash shield	1	\$	278.00
	Front LH fender	1	\$	970.00
38	Front LH fender splash shield	1	\$	278.00
30				

40	Radiator assy	1 1	\$ 1,673.80
41	Radiator fan assy	1	\$ 971.60
			\$ 21,589.90
		Parts less 10%	\$ 2,158.99
			\$ 19,430.91

No.	Special Nett Items	Qty	Ar	mount S\$	
1	Bonnet insulator clips	1set	\$	90.00	30m
2	Bonnet sealant	1	\$	100.00	K
3	Front grille clips	1set	\$	60.00	2000
4	Front bumper clips	1set	\$	80.00	3000
5	Support panel top cover clips	1set	\$	70.00	K
6	Front RH fender splash shield clips	1set	\$	60.00	×
7	Front LH fender splash shield clips	1set	\$	60.00	×
8	Radiator coolant	1	\$	100.00	X
9	Front number plate	1	\$	80.00	con
			+		
		1	\$	278.00	1

Total: \$ 978.00

No.	Labour and painting	A	mount S\$]
			1000.00	Co
1	Labour charges to remove, check, replace and reinstall	\$	1,200.00	600
	damages bodyparts. To panel beating, cut/weld and			
	realign all affected panels and areas	-		
2	Spray painting on affected areas and panels	\$	1,200.00	800
3	Check wiring and lighting system on affected areas	\$	80.00	40
4	Apply rust coating chemical on affected areas and panels	\$	80.00	30
5	Remove and replace aircon condenser and pipes to assist repair	\$	280.00	1008
6	Remove and replace radiator assy and hoses to assist repair	\$	280.00	100
7	Refocus and adjust headlamps assy	\$	100.00	40
8	Diagnose and reset control unit	\$	450.00	×
	Total:	S	3 670 00	

Agreed Amount: (Part by Part / Lump sum)

Tanfihm 97495749 wp 0//1/272 345pm

4/5 Resury nother report - To check consistency of accident

tanfihm @ /khanto.com - To check point prices

5 days.

Working	days:

 Spare Parts:
 \$ 19,430.91

 Special Nett:
 \$ 978.00

 Labour:
 \$ 3,670.00

Total Amount: \$ 24,078.91

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Repair Supplementary Estimate

Vehicle number: SLF1850	Date of survey:
Make & Model: Lexus IS250	Name of surveyor:
Chassis number:	Contacts:

No.	Description of spare parts	Qty	Ar	nount S\$
1	Air filter cover	1	\$	467.00
			\$	467.00
		Parts less 10 ^s	% \$	46.70
		Tota	1 \$	420.30

No.	Special Nett Items	Qty	Amount S\$
		Total:	\$ -

No.	Labour and painting	Amount S\$

		Total:	\$
Agreed Amount:	(Part by Part / Lump sum)		
Working days:			

Spare Parts: \$ 420.30 Special Nett: \$ -Labour: \$ -

Total Amount: \$ 420.30

Toufan Stulez.