



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22010726/Dny3q2 Date: 11/01/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLR 8425T	Veh. Inspected	SKT 122X	
Policy No.	P10626489R01	Coverage (\$)	0.00	
Claim No.	C10018287/JM	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	28/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	AUDI A3	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WAUZZZ8V7F1073187	Colour	WHITE	
Odometer	228951 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	235/35 R19	GOODYEAR	5 mm	
L/H Front Tyre	235/35 R19	GOODYEAR	5 mm	
R/H Rear Tyre	235/35 R19	GOODYEAR	5 mm	
L/H Rear Tyre	235/35 R19	GOODYEAR	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	25/10/2022	Inspection Date	28/10/2022	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #02-16 AMK AUTOPOINT SINGAPORE 568047			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	