

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI22010727/Avy3e2
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Di	ate:	01/02/2023
			C	ode:	AGI
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLT 5501R	Veh. Inspected		GBK 4219D
	Policy No.	P10644628R00	Coverage (\$)		0.00
	Claim No.	C10018244/CD	Excess (\$)		0.00
	Assign From	SALIZAWATI HAIZAR	Assign Date		28/10/2022
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV350	c.c		2488
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	JN1MC2E26Z0032042	Colour		GREY
	Odometer	62273 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	195 R15C	MAXMILER		6 mm
	L/H Front Tyre	195 R15C	MAXMILER		6 mm
	R/H Rear Tyre	195 R15C	MAXMILER		6 mm
	L/H Rear Tyre	195 R15C	MAXMILER		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	22/10/2022	Inspection Date		28/10/2022
	Survey held at	eld at AUTOMOBILE HUB ENTERPRISE			
		1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

6 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: