

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |  |                 |       |                       |  |
|---|--|--|-----------------|-------|-----------------------|--|
|   | SOMPO INSURAN                                  | ICE SINGAPORE PL   |                 | Ref:  | CS/SMO22010738/Any3e2 |  |
|   | 50 RAFFLES PLAC<br>SINGAPORE LANI              | CE #03-03<br>D TOWERSINGAPORE 048623   | I               | Date: | 16/01/2023            |  |
|   |  |  | •               | Code: | SMO                   |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM        |  |                 |       |                       |  |
|   | Insured Veh.                                   | GBC 5376T  | Veh. Inspected  |       | SNC 2661Y             |  |
|   | Policy No.                                     |  | Coverage (\$)   |       | 0.00                  |  |
|   | Claim No.                                      | CMTD2203902/AGC  | Excess (\$)     |       | 0.00                  |  |
|   | Assign From                                    | GRACE TEO  | Assign Date     |       | 28/10/2022            |  |
| 2. Vehicle Particulars & Condition                                |  |  |                 |       |                       |  |
|   | Make & Model                                   | VOLVO V60  | c.c             |       | 1969                  |  |
|   | Engine No.                                     | HIDDEN   | Year of Reg.    |       | 2021                  |  |
|   | Chassis No.                                    | YV1ZZL1TCN1085559  | Colour          |       | GREY                  |  |
|   | Odometer                                       | 8716 KM  | Steering        |       | IN ORDER              |  |
|   | Brakes   | IN ORDER   | Modification    |       | SPORTS RIM            |  |
|   | General  | GOOD   |                 |       |                       |  |
| 3.  | 3. Conditions of Tyres                         |  |                 |       |                       |  |
|   |  | Size   | Make            |       | Balance               |  |
|   | R/H Front Tyre                                 | 225/50 R18   | MICHELIN        |       | 6 mm                  |  |
|   | L/H Front Tyre                                 | 225/50 R18   | MICHELIN        |       | 6 mm                  |  |
|   | R/H Rear Tyre                                  | 225/50 R18   | MICHELIN        |       | 6 mm                  |  |
|   | L/H Rear Tyre                                  | 225/50 R18   | MICHELIN        |       | 6 mm                  |  |
| 4.  | Description of Damages                         |  |                 |       |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. |  |                 |       |                       |  |
|   | DAMAGES SEE DETAILS.                           |  |                 |       |                       |  |
| 5.  | General Information                            |  |                 |       |                       |  |
|   | Accident Date                                  | 27/10/2022   | Inspection Date | )     | 31/10/2022            |  |
|   | Survey held at                                 | GREEN FOREST AUTOMOBILE  |                 |       |                       |  |
|   |  | 8 KAKI BUKIT AVENUE 4<br>#05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875  |                 |       |                       |  |
| 5a.   |  | Remarks  |                 |       |                       |  |
|   |  | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                 |       |                       |  |
| 5b.   |  | Estimate Days of Repair  |                 |       |                       |  |
|   | ESTIMATED NOR                                  | ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days   |                 |       |                       |  |