(08/1?

ASS. REC. BY: NAZ

REF: CTI

JU PIP

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S	O/S

Bal. or Market Value: _____ X X Y

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD 4433 S Yr Regn: 18 / 03/2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover / Truck / Trailer or _____

Make: HYUNDAI IONIQ 43 c.c 1,580

Colour BLUE A/C: (Insured) / Std / NI / NA

Sp.Reading 501,805 T/Radio: (Insured) / Std / NI / NA

Eng/No: _____

C/No: KMHC851CVLU190643

Gen. Cond: Good / (Fair) / Poor / Burnt

Steering: (Inorder) / Jammed / Leaked / Burnt or _____

Brake: (Inorder) / Jammed / Leaked / Burnt or _____

Modl : NII / S/Rim / (STD) A/Rim or _____

Tyre Size: F: 195 / 65 R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or WESTLAKE

Front		Rear	
R/Bal.	4 mm	R/Bal.	4 mm
L/Bal.	4 mm	L/Bal.	4 mm
D.O.A.	23/10/2022	D.O.I.	25/10/2022

Survey held at EDGE COYANG

Des. of Damages : Frt / (Rear) / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

CTI PIP

Date / Time	Action / Instruction

Date/Time, File Pass to? 1) _____ ☐ : Preli. Report ☐ : Final Report

Date/Time, File Return to? 2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____) ☐ : Interview ($ _____) ☐ : Tech. Invs ($ _____) ☐ : Weekend ($ _____)

Report Format : _____

Lump Sum / I.B.I: ($ _____)

Survey Fee:	
Transportation:	
___S + RS___SI	
Photos	
Others	
TOTAL	