

ASS. REC. BY:

REF: SMOLKenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: B46k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBF 3748B Yr Regn: 09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: NIS Cabstar c.c. 2953Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 165173 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN/SC2F2420858963Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: ML / S/Rlm / STD A/Rlm orTyre Size: F: B.P 195R15XPR: Triangle 155R12X8(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front: _____ Rear: _____

R/Bal. 9 mm R/Bal. 88 mmL/Bal. 9 mm L/Bal. 88 mmD.O.A. 24/10/22 D.O.I. 31/10/2022Survey held at 2-30pmDes. of Damages Front / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Check company logo & sticker wrapping insured or not??

Date/Time, File Pass to?

☐: Prell. Report

1)

☐: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + RS \$

Fees:

Others:

Add Fee: ☐: Site Insp (\$)☐: Interview (\$)☐: Tech Invs (\$)☐: Weekend (\$)

Report Format:

Lump Sum / I.B.I. (\$)

TOTAL

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBF3748 B
OD/SOMPO

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623

TEL: 64616555

FAX: 62213302

ATTN: Motor Claim Department

Claim No: ES2291117

Estimate No: ES2291117/YISHUN

Date: 31 Oct 2022

Policy No: D22MTPCVE002416

Veh Reg No: GBF3748B

Make/Model: NISSAN NISSAN
CABSTAR 3.0 5M/T ABS
2DR 2WD EURO

Chassis No: JN1SC2F24Z0858963

Engine No: ZD30013890N

Reg. Date: 27/09/2016

WS Ref: OD/SOMPO

Claim Type: Own Damage

Accident Date: 24/10/2022

Not Authorised
1/1 Rmp &
Returning After Paint
6 days

Estimate Repair Cost to Vehicle No : GBF3748B

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Cost Plus				
1 FRONT BUMPER	450.00	1 PC	450.00	✓
2 LH HEADLAMP	280.00	1 PC	280.00	✓
3 LH HEADLAMP LOWER GARNISH	60.00	1 PC	60.00	✓
4 FRONT GRILLE	275.00	1 PC	275.00	✓
5 FRONT GRILLE LOGO	65.00	1 PC	65.00	✓
6 FRONT PANEL	650.00	1 PC	650.00	✓
7 WIPER PANEL	290.00	1 PC	290.00	✓
8 LH WIPER ARM CAP	10.00	1 PC	10.00	✓
9 FRONT WINDSCREEN GLASS	480.00	1 PC	480.00	✓
10 FRONT WINDSCREEN GLASS MOULDING	210.00	1 PC	210.00	✓
11 AIRCON EVAPORATOR	1,350.00	1 PC	1,350.00	✓
12 FRONT RH MIRROR	120.00	1 PC	120.00	✓
13 FRONT RH MIRROR STAY	140.00	1 PC	140.00	✓
14 FRONT LH MIRROR	110.00	1 PC	110.00	✓
15 FRONT LH MIRROR STAY	140.00	1 PC	140.00	✓
16 FRONT LH MIRROR COVER (ROUND)	18.00	1 PC	18.00	X
17 FRONT LH MIRROR COVER (RECTANGLE)	68.00	1 PC	68.00	?
				4,716.00
Special Net				
18 FRONT NUMBER PLATE	20.00	1 PC	20.00	✓
19 FRONT WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
20 ERP BRACKET	20.00	1 PC	20.00	✓
				80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department

Claim No: ES2291117
Estimate No: ES2291117/YISHUN
Date: 31 Oct 2022
Policy No: D22MTPCVE002416
Veh Reg No: GBF3748B
Make/Model: NISSAN NISSAN
CABSTAR 3.0 5M/T ABS
2DR 2WD EURO
Chassis No: JN1SC2F24Z0858963
Engine No: ZD30013890N
Reg. Date: 27/09/2016

WS Ref: OD/SOMPO
Claim Type: Own Damage
Accident Date: 24/10/2022

Estimate Repair Cost to Vehicle No : GBF3748B

Description	U/Price	Quantity	Cost S\$	Amount S\$
Labour				
21 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
22 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
23 REMOVE & REFIX DASHBOARD	280.00	1 LA	280.00	2501
24 REMOVE & REFIX FRT BUMPER,HEADLAMPS,GRILLE & ATTACHMENT,REPAIR FRT INNER LFOOR PANEL,DASH PANEL,FRT CROSS MEMBER,CUT,WELD & RENEW FRT BODY PARTS	900.00	1 LA	900.00	7001
25 TO STRAIGHTEN FRT LH CHASSIS,REPAIR & REALIGN CABIN POSITION	300.00	1 LA	300.00	?
26 PUTTY & RESPRAY PAINT FRT GRILLE,FRT PANEL,WIPER PANEL,CORNAL PANEL,INNER FLOOR PANEL,DASH PANEL	950.00	1 LA	950.00	7001
27 TO REWRITE ADVERTISEMENT	120.00	1 LA	120.00	?
28 TO WRAPPING ON FRT PORTION	600.00	1 LA	600.00	?

3,350.00

* Airbag Light 'ON' - to further check ?

Total S\$ 8,146.00
Add GST @ 7% 570.22
Total Amount payable S\$ 8,716.22

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 663H

Vehicle Details

Vehicle No.: GBF3748B

Vehicle to be Exported: No

Intended Deregistration Date: 27 Oct 2022

Vehicle Make: NISSAN

Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5

Primary Colour: Silver

Manufacturing Year: 2016

Engine No.: ZD30013890N

Chassis No.: JN1SC2F24Z0858963

Maximum Power Output: -

Open Market Value: \$24,942.00

Original Registration Date: 27 Sep 2016

First Registration Date: 27 Sep 2016

Transfer Count: 1

Actual ARF Paid: \$1,248.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Sep 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$47,845.00

COE Rebate Amount: \$18,737.00

Total Rebate Amount: \$18,737.00

The information contained herein is correct as at 27 Oct 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 27/10/2022 18:42 (SGT)
Reported by Driver
Date of Accident 24/10/2022 12:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information LENTOR AVE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBF3748B
INSURED/POLICYHOLDER
Is company? Yes
Name Of Registered Owner LYRECO (SINGAPORE) PTE LTD
Company Reg No 2XXXXXX663H
Email Address rasupalsamy2601@gmail.com
Mobile Phone No (Phone) +60-164447713
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Nissan
Model CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Manual
CC 2953

INSURANCE COMPANY

Name of Insurance Company Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number D22MTPCVE002416

DRIVER


Name of Driver MUDIARASU S/O PALSAMY
NRIC No SXXXX611H
Date Of Birth 26/01/1957
Occupation Outdoor

Describe Circumstance of the Accident

** NOTE : PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

(/) Claim Own Policy () Claim Third party () Reporting Only
() Claim OD/ TP at other workshop ()

Sketch Plan



A GBF3748B

B- 5658E (Lorry)

DOA: 24/10/22 12:30pm

I could not stop on time & had collided onto 5658E

rear portion.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

P. M. M. in

Driver's Signature (if driver is not the policyholder) / Date & Time

(YS) mg 27/10/22
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)