

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE		Ref:	CS3/ASM22010788/Rqy3e2		
	8 SHENTON WAY SINGAPORE 0688		Date:	09/11/2022		
	ATTN: KHOR SAW	THENG		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 7053B	Veh. Inspecte	d	FBN 6625K	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04BO9	Excess (\$)		0.00	
	Assign From	KHOR SAW THENG	Assign Date		28/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA AEROX GDR155A CVT	c.c		155	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MH3SG4640JJ041887	Colour		MULTI COLOUR	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	110/80-14	PIRELLI		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	140/70-14	PIRELLI		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.					
5.	General Information					
	Accident Date	23/09/2022	Inspect Date /	Time	31/10/2022 ( 03:36 PM )	
	Survey held at	y held at HUA CHIN (2000) TRADING MOTOR SVC CENTRE				
		50, BUKIT BATOK STREET 23, #02-02 MIDVIEW BUILDING SINGAPORE 659578				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000					
5b. Estimate Days of Repair						
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/ASM22010788/Rqy3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser