

◀ Service Request Details

Claim	S2M04D2Z
Reference	CS/ASM22010791/Svy3m4 
Loss Date	17 October 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	18 Oct 2022 12:18:24 PM
Request Date	31 October 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	FBT9568R
Vehicle	
Registration #	
Make	TPVD BIKE
Model	YAMAHA

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

HO Winnie

winnie.ho@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRI TP PDF.pdf	Other	Other	do not reply	

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2207535.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 LKKInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 LKKAdjustment.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	6 December 2022
 REPLY FROM TP.msg.msg	Legal	Others	KUMAR Shailendra	31 October 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 PRS TP.pdf.pdf	Legal	Others	KUMAR Shailendra	28 October 2022
 PRI TP EMAIL FROM SOLICITOR.msg.msg	Legal	Others	KUMAR Shailendra	28 October 2022
 FBT9568R TP GIA.pdf.pdf	Reports & Statement	GIA Report	KUMAR Shailendra	28 October 2022
 SJ0G22AI0006-SH7557Y.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	18 October 2022