

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22010793/Svy3m4	
	8 SHENTON WAY SINGAPORE 0688		Date:	08/11/2022		
	ATTN: LOW GARN	ET		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SHA 2411J	Veh. Inspected	I	SMV 4129S	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M04DD1	Excess (\$)		0.00	
	Assign From	LOW GARNET	Assign Date		31/10/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	TOYOTA CAMRY	c.c		2487	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JTNB23HK403074834	Colour		WHITE	
	Odometer	55852 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	MICHELIN		6 mm	
	L/H Front Tyre	215/55 R17	MICHELIN		6 mm	
	R/H Rear Tyre	215/55 R17	MICHELIN		7 mm	
	L/H Rear Tyre	215/55 R17	MICHELIN		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
5. General Information						
	Accident Date	22/10/2022	Inspect Date /	Time	31/10/2022 (05:30 PM)	
	Survey held at	3 MOTORWERKZ				
		25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800				
5a.	Remarks					
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PLE	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair						
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				

Report Ref No. CS3/ASM22010793/Svy3m4

Inspected By

S MOHAMED IRFAN BIN MOHAMED IQUBAL

Asst. Automotive Assessor

K.K.LAU CPT(RET)

DEOD Auto Occasions OAE Licensed American

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$