

 Service Request Details

Claim	S2M04DD1
Reference	CS3/ASM22010793/Svy3m4 
Loss Date	22 October 2022
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	24 Oct 2022 3:27:55 PM
Request Date	31 October 2022
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident	SMV4129S
Vehicle	
Registration #	
Make	TPVD- Toyota
Model	Camry

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

LOW Garnet

garnet.low@axa.com.sg

Additional Instructions

Messages1InvoicesHistoryDocumentsAssessmentMetricsNotes

Document TypeDocument SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP PRI PDF.pdf.pdf	Other	Other	do not reply	

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2206929.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	9 November 2022
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	9 November 2022
 Resurvey Photo-2.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	9 November 2022
 Resurvey Photo-1.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	9 November 2022
 LKKPhoto.pdf.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	9 November 2022
 SMV 4129S IA PRS.pdf.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	4 November 2022
 INSD GIA REPORT - SHA2411J.pdf.pdf	Reports & Statement	GIA Report	PODUVAL Akash	31 October 2022

NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 TP GIA REPORT.pdf.pdf	Reports & Statement	GIA Report	PODUVAL Akash	31 October 2022
 TP PRI PDF.pdf.pdf	Letters and Correspondence	Workshop	PODUVAL Akash	31 October 2022
 SJ0G22AM0013-SHA2411J.pdf.pdf	Reports & Statement	Accident statement	STACEY Ng Pei Sze 2	24 October 2022