



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010816/Kvy3q2	
			Date: 22/11/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SME 7890X	Veh. Inspected	SMQ 8328J	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2203919/SYH	Excess (\$)	0.00	
Assign From	MELVIN YE	Assign Date	31/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1987	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JTDGJ20W805001766	Colour	METALLIC GREY	
Odometer	289298 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	GOODYEAR	8 mm	
L/H Front Tyre	195/65 R15	GOODYEAR	8 mm	
R/H Rear Tyre	195/65 R15	KAPSEN	4 mm	
L/H Rear Tyre	195/65 R15	KAPSEN	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2022	Inspection Date	01/11/2022	
Survey held at	MASSIVE TRADING & AUTO BLK 203 HOUGANG ST 21 #04-91 SINGAPORE 530203			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	