



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22010818/Eqy3e2 Date: 02/12/2022 Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLR 9516H
	Policy No.	D22MTPV01013340	Coverage (\$)	0.00
	Claim No.	CMTD2203891/RC	Excess (\$)	250.00
	Assign From	MELVIN YE	Assign Date	31/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	RU11208151	Colour	BROWN
	Odometer	85118 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	CONTINENTAL	4 mm
	L/H Front Tyre	215/60 R16	CONTINENTAL	4 mm
	R/H Rear Tyre	215/60 R16	CONTINENTAL	4 mm
	L/H Rear Tyre	215/60 R16	CONTINENTAL	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/10/2022	Inspection Date	01/11/2022
	Survey held at	PUAN CHEW MOTOR WORK PTE LTD BLK K, PANDAN LOOP IND. EST #01-12 SINGAPORE 128219		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	