

INC

7072

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHA1867J**
 MAKE **HYUNDAI**
 MODEL **IONIQ**

DATE: **20.10.22**
 MVA **JUMANI**
 DOA: **18.10.22**

CL/Sum)
INCOME

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
1	FRT DOOR ASSY LH			\$1,797.20	<i>Ry</i>
1	REAR DOOR ASSYLRH			\$2,147.90	<i>Ry</i>
1	FRT FENDER EMBLEM			\$26.60	<i>net</i>
1	FRT DOOR HANDLE RH			\$234.80	<i>Ry</i>
1	FRT FENDER LH			\$588.80	<i>Ry</i>
1	REAR WHELL CAP LH			\$346.40	<i>net</i>
1	REAR BUMPER ASSY			\$459.40	<i>Ry</i>
SUB TOTAL				\$5,601.10	
LESS 20%				\$1,120.22	
DISCOUNTED TOTAL				\$4,480.88	
FRT DOOR COMFORT LOGO				<i>cut</i> \$75.00	NET
REAR DOOR APPS LOGO				<i>net</i> \$80.00	NET
REAR BUMPER MAT				<i>X</i> \$50.00	NET
				\$205.00	
Labour Charge					
PANEL BEATING				<i>\$25</i> \$800.00	
SPRAY PAINT				<i>✓</i> \$1,200.00	
REMOVE / REFIX DOOR PARTS				<i>X</i> \$240.00	
CHECK WIRING				<i>X</i> \$50.00	
TUFF KOTE				<i>X</i> \$60.00	
TOTAL LABOUR				\$2,350.00	
ESTIMATE TOTAL				\$7,035.88	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 27445743
wp, 20/10/22 2:50pm
CL/Sum after report
Tanpin C/Manthorn
2-3 days

Date/Time: 20.10.2022 08:27

Page : 1

am: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5068995

JC NO305533692

OMER

REGN NO:

SHA1867J

MILEAGE

IS COMFORT TRANSPORTATION PTE LTD

OMER NO. 7010045

TESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

MAKE:

HYUNDAI

FUEL

E 1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 19.10.2022 16:35

YR OF MANU.

26.06.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU164303

COMPLETION DATE/TIME:

OUNT CARD NO.

JOB DESCRIPTION

cident Date: 18.10.2022


ATURE: 3P.18.10.22/C

/NO


LABOR CODE

DESCRIPTION


FRONT



LEFT SIDE



REAR



RIGHT SIDE

OKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

ledgement Slip

Exit Pass

No.: SHA1867J

JU INCOME

Vehicle No.:

SHA1867J

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard