

ASS. REC BY: T. J. M.

REF:

INL

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Lim TS

Vehicle: IN / OUT

Veh No: SHB 4280B Yr Regn: 2020 Feb

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.C. 1798

Colour: Blue A/C: Insured / Std / NI / NA

Spl. Reading: 204604 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: STDKRB3F4003091170

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 31/10/22

Survey held at Gulfport Bayang

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass 10?

☐ : Preli. Report

☐ : Final Report

1) _____

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Others _____

TOTAL _____

Add Fee: _____

☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Report Format: _____

Lump Sum / L.B. / % _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

SAS-KIV

DATE: 31.10.22

MODEL: Toyota Prius G4A

VEHICLE NO.: SHB4280S

INSURANCE: INCOME → FBL1822B

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$551.89 <i>th</i>
	Rear Bumper Lower Cover	1		\$654.96 <i>x</i>
	Rear Bumper Clips	10	\$2.20	\$22.00 <i>net</i>
	Rear Bumper Side Bracket LH	1		\$112.70 <i>?</i>
	TailLamp Upper LH	1		\$557.90 <i>x</i>
	TailLamp Lower LH	1		\$570.00 <i>own</i>
	SUB TOTAL			\$2,469.45
	LESS 25%			\$617.36
	DISCOUNTED TOTAL			\$1,852.09
	Rear Bumper Mat	1	<i>net</i>	\$50.00
				NETT
	PARTS TOTAL			\$1,902.09
	Labour Charge			
	Panel Beating		350	\$400.00
	Spray Painting Charge		250	\$300.00
	Check Lightings		30	\$40.00
	Remove/Refix Reverse Sensor		30	\$120.00
	TOTAL LABOUR			\$860.00
	ESTIMATE TOTAL			\$2,762.09

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taufik 97495749
 'WP' 31/10/22 330pm
 c/s Resing after repair
 ~2 days
 Taufik & Lkh auto wu

KK Auto Consultants hereby notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during survey
 • Parts prices are subject to market fluctuation
 • Third party survey is on a non-binding basis
 • No illegal modification is allowed
 • Supplementary items are subject to final approval by the insurance company

Acknowledged by:
 Signature:
 Date:

COMFORTDELGRO ENGINEERING

number of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

388 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

320 Ubi Road Singapore 408649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 31.10.2022 10:06

Page : 1

m: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5131981

JC NO305534874

MER

COMFORT TRANSPORTATION PTE LTD

7010045

MER NO.

SS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

R) 65508755

(O)

P)

JNT CARD NO.

REGN NO:

SHB4280B

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4A31.10.2022 08:10

DATE/TIME IN

YR OF MANU

28.02.2020

TARGET DATE

CHASSIS CODE

JTDKB3FU003091140

COMPLETION DATE/TIME:

JOB DESCRIPTION

Ident Date: 29.10.2022

DURE: 3P 29.10.2022

IO

0010


LABOR CODE

PB

DESCRIPTION

LUMPSUM REPAIR-SHB4280B-TP

FRONT



ID & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

Vehicle No.:

SHB4280B

SHB4280B

LIMITS

Service Advisor

Signature/Date

Name of Service Advisor

Date

ed to Service Reception upon collection

To be kept by Security Guard