

Steve

CC4/LPC 22010859/PA3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMX 708 Yr Regn: 23/7/20

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Serena c.c. 1198Colour: White A/C: Insured / Std / NI / NASp. Reading: 51782 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1ERAC 7720000607

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S Rim / STD A/Rim or

Tyre Size: F: 195/50R16R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: Pirelli

Front Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 27/10/22 D.O.I. 31/11/22Survey held at VAG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV-1491K

Order/Time, File Pass to?

☐ : Prelim. Report☐ : Final Report

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.L. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$1

Photos

Others

TOTAL

Singapore 608586

www.avantage.sg

3/11/22, 11:30L

m, n

3 dys, P/P, my BL G

Chassis No : JN1EBAC27Z0000607

[illegible]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from the Insurance Company

Acknowledged by Repairer

Signature: _____

Date: