

(08/11/13) wef

ASS. REC. BY:

REF:

CS/MSG22010854/Rgy³

9853

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SM2 3727B

at Workshop m/s WIN AUTOMOTIVE

of 60, JLN Lam Hunt #04-53

Insured: MSG

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 98K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SM2 3727B Yr Regn: 2021 / APR

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA RAISE 1.0X CVT c.c. 996

Colour: BLUE

A/C: Insured / Std / NI / NA

Sp. Reading: 21534

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: A200A 0113748

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

195/65R16

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 27/10/22

D.O.I. 01/11/22

Survey held at

WIN AUTOMOTIVE

Des. of Damages: ☒ Front / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 58K

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

) S + RS SI

☐ : Interview (\$ _____)

) Photos

☐ : Tech. Invs (\$ _____)

) Others

Report Format :

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	985J
Vehicle No.:	SMZ3727B
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Nov 2022
Vehicle Make:	TOYOTA
Vehicle Model:	RAIZE 1.0X CVT
Primary Colour:	Blue
Manufacturing Year:	2021
Engine No.:	1KRK124218
Chassis No.:	A200A0113745
Maximum Power Output:	72.0 kW (96 bhp)
Open Market Value:	\$17,505.00
Original Registration Date:	23 Apr 2021
First Registration Date:	23 Apr 2021
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Apr 2031
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	22 Apr 2031
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$41,996.00
COE Rebate Amount:	\$35,579.00
Total Rebate Amount:	\$39,329.00

The information contained herein is correct as at 02 Nov 2022

OK

Toyota Raize 1.0A X

Overview

[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)**Price****\$96,800****Depreciation** ⓘ

\$11,410 /yr

[View models with similar depre](#)**Reg Date**

05-Feb-2021

(8yrs 3mths 2days COE left)

Mileage

23,498 km (13.5k /yr)

Manufactured ⓘ

2020

Road Tax ⓘ

\$392 /yr

Transmission

Auto

Dereg Value ⓘ

\$38,455 as of today (change)

OMV ⓘ

\$18,667

COE ⓘ

\$42,000

ARF ⓘ

\$5,000

Engine Cap

996 cc

Power

72.0 kW (96 bhp)

Curb Weight ⓘ

970 kg

No. of Owners ⓘ

1

Type of Vehicle

SUV