

ASS. REC. BY:

REF:

LPC / 22 010866 / kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

 Remark: The veh had commenced its
repair at the time of inspection.


Bal. or Market Value:

833/c

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

18

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YN 8868R

Yr Regn:

08.14

Type: M.Car / M.Cycle / Bus / Van / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Carter

c.c

2988

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

1CEBFI EA 00165

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/75R17.5

R:

(D)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

AKing

Front

R/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

5/10/22

Rear

R/Bal.

66

mm

L/Bal.

66

mm

D.O.I.

2/11/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rm O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Paints

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

金興(雙)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20/21

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

OD Longac

(10)

Not Authorized

LI Sing &

Returning After Rain

Ex & Food

18 days

No. : 32611

Date : 01-Nov-2022

PAGE : 1

Your Reference : Z22VC05012830

Accident Date : 05-Oct-2022

Our Ref : 022356 / ANGIE

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSE

Singapore 199555

ESTIMATED COST OF REPAIR FOR MITSUBISHI CANTER (2998cc) (2014) YN8868R

1 pc front cabin assy
1 pc dashboard assy
1 pc dashboard reinforcement
1 pc air con blower
1 pc air con cooling coil
1 pc air con heater unit
4 pcs dashboard louver
1 pc dashboard louver inner duct
1 pc dashboard meter
1 pc cabin seats assy
1 pc steering wheel
1 pc steering wheel cover
- (top/lower)
1 pc steering column
1 pc steering column shaft
1 pc steering column cone
1 pc signal/wiper hand indicator
1 pc steering box
1 pc wooden flatbed partition

Ry 10,500.00 c ✓
Bo 7,500.00 c ✓

Jm 3,200.00 c ✓
CM 3,500.00 c ✓

24,700.00

Add 15% : 3,705.00

28,405.00

Labour to remove/replace above
parts and re-align affected portion

3200.
4,000.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

Your Reference : Z22VC05012830
Our Ref : 022356

Page : 2

No. : 32611

To putty and respray affected
portion.

chassis alignment.

wheel alignment.

1500/ 1,800.00

1000/ 1,200.00

80.00 X

Total : SS35,485.00

Singapore Dollars Thirty Five Thousand Four Hundred
and Eighty Five Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 27/10/2022 20:54 (SGT)
Reported by Driver
Date of Accident 05/10/2022 10:50 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number YN8868R

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner CHIN WAH PAINTS PTE LTD
Company Reg No 1XXXXX567W
Email Address TAIWEECHAN@GMAIL.COM
Mobile Phone No (Phone) +65-62533222
Alternative Phone No +65-98208443

VEHICLE PARTICULARS

Manufacturer Mitsubishi
Model Canter
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Manual
CC 0

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd
Policy Number / Cover Note Number Z22VC05012830

DRIVER

Name of Driver YEO ENG KEID
NRIC No SXXXX115B
Date Of Birth 21/04/1961
Occupation Indoor



SINGAPORE POLICE FORCE

Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000



T/20221019/2033

2 of 3

Report No. T/20221019/2033

CONTINUATION OF REPORT

Driver				
Name	Yeo Eng Keid		ID No.	S1487115B
Related Vehicle	NIL		Contact No.	84201934
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 5 Oct 2022 at about 10.50 a.m., I was driving my company lorry YN8868R along PIE towards Airport. It was drizzling. I was travelling behind a tipper truck and I heard a bang. I could not manage to stop in time and collided onto the rear of the tipper truck. Due to the accident I was trapped in my lorry and the front portion is badly damaged. I was then being extracted by SCDF and was conveyed to the NUH. I was given 24 days of MC.

Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

567W

Vehicle Details

Vehicle No.:

YN8868R

Vehicle to be Exported:

Yes

Intended Deregistration Date:

27 Oct 2022

Vehicle Make:

MITSUBISHI

Vehicle Model:

CANTER FEB71ER4SDEC

Primary Colour:

White

Manufacturing Year:

2014

Engine No.:

4P10B26206

Chassis No.:

FEB71EA00165

Maximum Power Output:

-

Open Market Value:

\$32,311.00

Original Registration Date:

06 Aug 2014

First Registration Date:

06 Aug 2014

Transfer Count:

0

Actual ARF Paid:

\$1,616.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

05 Aug 2024

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$10,005.00

COE Rebate Amount:

\$1,775.00

Total Rebate Amount:

\$1,775.00

The information contained herein is correct as at 27 Oct 2022

OK