



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI22010925/Avy3q2 Date: 24/04/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKM 3318R	Veh. Inspected	SKC 9000U
Policy No.		Coverage (\$)	0.00
Claim No.	C10018341/CD	Excess (\$)	0.00
Assign From	SALIZAWATI	Assign Date	02/11/2022
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	B.M.W. 530E	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBAJA92020G758770	Colour	WHITE
Odometer	60341 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	245/35 R20	ALVENTI	6 mm
L/H Front Tyre	245/35 R20	ALVENTI	6 mm
R/H Rear Tyre	245/35 R20	ALVENTI	6 mm
L/H Rear Tyre	245/35 R20	ALVENTI	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	27/10/2022	Inspection Date	15/11/2022
Survey held at	FONG MOTORS 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	