



QUOTATION

Customer :

NO. : 42005

- Rev. 1

AXA INSURANCE PTE LTD

8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

DATE : 31/10/2022

CLAIM NO. : 12036

POLICY NO. : MC/00914099/01

ATTN: MOTOR CLAIMS DEPT

FROM : STEPHANIE

VEHICLE NO. : FBK6058M
MAKE/MODEL : YAM / YBR125

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	COVER TAIL RH (RED) P/N: 53007 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$90.00	90.00
2	COWLING FRONT (RED) P/N: 52897 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$133.00	133.00
3	CRASH BAR P/N: 35878 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$203.00	203.00
4	HEADLAMP ASSY P/N: 43129 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$105.00	105.00
5	LABOUR P/N: 06766 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$63.00	378.00
6	LAMP SIGNAL FRONT RH P/N: 43432 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
7	LAMP SIGNAL REAR RH P/N: 44191 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00
8	LEVER BRAKE P/N: 26343 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
9	METER ASSY P/N: 42063 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$264.00	264.00

*42005 *



S/N	Description	Action	Qty	Unit Price	Amount
10	MIRROR RH P/N: 58187 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00
11	MUDGUARD FRONT (RED) P/N: 42220 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
12	PROTECTOR EXHAUST P/N: 68051 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$77.00	77.00
13	PROTECTOR EXHAUST CAP P/N: 68052 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00
14	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	16.00
15	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$27.00	27.00
16	TRANSPORT CHARGES P/N: 07169	Supply/Install	1.00	\$56.00	56.00

SUB TOTAL	\$1,543.00
GST @ 7 %	\$108.01
GRAND TOTAL (SGD)	\$1,651.01

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*42005 *

bizSAFE₃



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/10/2022 23:49 (SGT)
Reported by	Driver
Date of Accident	22/10/2022 15:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	846 Yishun ring road
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBK6058M
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	BAN HOCK HIN CO PTE LTD
Company Reg No	1XXXXX288K
Email Address	raymond@bhh.com.sg
Mobile Phone No	(Phone) +65-62816520
Alternative Phone No	(Office) +65-62816520

VEHICLE PARTICULARS

Manufacturer	Yamaha
Model	YBR125
Variant	
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Reporting only
Vehicle Category	Motorcycle
Transmission	Manual
CC	125

INSURANCE COMPANY

Name of Insurance Company	Direct Asia Insurance (Singapore) Pte Ltd
Policy Number / Cover Note Number	MC/00914099

DRIVER

Name of Driver	Gao Xiang
Work Permit No	GXXXX244N
Date Of Birth	15/11/1997
Occupation	Outdoor

Date Of Driving Pass	15/11/2021
Driving experience	11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-93611507
Alt. Phone Number	-
Email Address	workshop@bhh.com.sg
Address	Na
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

My bike FBK6058M was parked at the open carpark of Blk 846 Yishun Ring Road. And my friend witness that the 3rd party SMD8331S had make a reverse and hit onto the company bike. My manager managed to take some photos and exchange particulars with the driver. No injuries was involved at the scene.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMD8331S
Vehicle Manufacturer	Mercedes
Vehicle Model	E300
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	Ong Beng Chong
NRIC No	SXXXX207J
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Witnessed By Reporting Officer
Muhammad Sumardi Bin Mohd Affandi

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

REFER TO ATTACHED ACCIDENT DIAGRAM



ACCIDENT DIAGRAM Ver. 30042021

846 NICHAN A FBK 6058 M

RING RD B SMD 83318

(REVERSE BACK)

UNIQUE OF HOW IT HAPPEN

Policyholder's Signature

Date & Time:

[Signature]

Driver's Signature

(If driver is not the policyholder)

Date & Time:

VERIFIED BY AJAX MARS (ARC)

REPORTING OFFICER

MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Describe Circumstances of the Accident

My bike FBK6058M was parked at the open carpark of Blk 846 Yishun Ring Road. And my friend witness that the 3rd party SMD83315 had make a reverse and hit onto the company bike. My manager managed to take some photos and exchange particulars with the driver. No injuries was involved at the scene

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed By Reporting Officer
Muhammad Sumardi Bin Mohd Affandi

Witnessed by Reporting Centre
Personnel

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SMD8331S

Date of Accident

22/10/2022 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance AXA Insurance Pte Ltd

Period of Insurance 26/10/2021 - 25/10/2022

Requested By Tan Chok Lok (Ban Hock Hin C...

Requested Date 27/10/2022 15:43

Payment details

Request Amount: **S\$1.87**GST Amount: **S\$0.13**Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

Vehicle Details

Vehicle No.	Make / Model
FBK6058M	YAMAHA / YBR125
Vehicle Type :	Vehicle Attachment 1 :
P00 - Passenger Motorcycle/Autocycle/Moped	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	LBPREF101000055618
Propellant :	Engine No. :
Petrol	E3F5E040622
Motor No. :	Engine Capacity :
-	124 cc
Power Rating :	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
320 kg	114 kg
Year Of Manufacture :	Original Registration Date :
2015	05 Nov 2015
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$6,201.00	04 Nov 2025
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
04 May 2023	-
Inspection Due Date :	Intended Transfer Date :
04 Nov 2023	01 Nov 2022
CO2 Emission :	CEV/VES Rebate Utilised Amount :