

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI22010945/Avy3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date:	18/11/2022	
			Code:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SGF 1973X	Veh. Inspected	GBJ 2700Z	
	Policy No.	P10723027R00	Coverage (\$)	0.00	
	Claim No.	C10018393/CD	Excess (\$)	0.00	
	Assign From	SALIZAWATI	Assign Date	02/11/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	RENAULT KANGOO	c.c	1461	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	VF1FWT8H361486566	Colour	GREY	
	Odometer	88983 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
	L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
	R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
	L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	31/10/2022	Inspection Date	02/11/2022	
	Survey held at	Survey held at TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

9 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: