

ASS. REC. BY:

REF:

SMU/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 863k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No:

SNE 7951P

Yr Regn:

04, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make:

Lexus

ES250

c.c

2494

Colour:

n-Black

A/C:

Insured / Std / NI / NA

Sp. Reading

156350

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTHBT1GG002077985

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

29/10/22

D.O.I.

3/11/2022

Survey held at

12pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

) \$ + RS. \$

) Extras

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Authorised
Referring B4 pain
Ex TBA

6 days

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S: SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623
TEL: 64616555 FAX: 62213302
ATTN: Motor Claim Department
WS Ref: OD/SOMPO/AMK
Claim Type: Own Damage
Accident Date: 29/10/2022

Claim No: ES2291125
Estimate No: ES2291125/AMK
Date: 02 Nov 2022
Policy No: D22MTPV01008996
Veh Reg No: SNE7951S
Make/Model: LEXUS ES250
Chassis No: JTHBJ1GG002077985
Engine No: 2ARF002668
Reg. Date: 28/04/2015

Estimate Repair Cost to Vehicle No : SNE7951S

Description	U/Price	Quantity	Cost	Amount
			SS	SS
Cost Plus				
1 FRONT BUMPER	390.00	1 PC	390.00	✓
2 FRONT BUMPER REINFORCEMENT	195.00	1 PC	195.00	?
3 FRONT BUMPER SPONGE	70.00	1 PC	70.00	?
4 FRONT BUMPER LH SIDE RETAINER	36.00	1 PC	36.00	✓
5 FRONT BUMPER LH FOG LAMP	105.00	1 PC	105.00	✓
6 FRONT BUMPER LH FOG LAMP BRACKET	70.00	1 PC	70.00	✓
7 FRONT BUMPER LH FOG LAMP CHROME COVER	65.00	1 PC	65.00	✓
8 FRONT BUMPER INNER TOP RUBBER	45.00	1 PC	45.00	✓
9 FRONT BUMPER LH WIPER NOZZLE ASSY	220.00	1 PC	220.00	✓
10 FRONT BUMPER LH WIPER NOZZLE COVER	16.00	1 PC	16.00	✓
11 FRONT BUMPER LH WIPER NOZZLE HOSE TUBE	75.00	1 PC	75.00	✓
12 FRONT BUMPER CLIP	1.50	8 PC	12.00	✓
13 FRONT GRILLE HOUSING	390.00	1 PC	390.00	?
14 FRONT GRILLE OUTER CHROME	140.00	1 PC	140.00	✓
15 FRONT GRILLE LOGO	195.00	1 PC	195.00	?
16 FRONT LH FENDER	360.00	1 PC	360.00	✓
17 FRONT LH FENDER INNER SHIELD	125.00	1 PC	125.00	?
18 FRONT LH FENDER EXTENSION BRACKET	62.00	1 PC	62.00	✓
19 FRONT LH FENDER SIDE BRACKET	29.00	1 PC	29.00	✓
20 FRONT LH FENDER INNER TOP PROTECTOR	95.00	1 PC	95.00	✓
21 FRONT LH FENDER INNER TOP PROTECTOR CLIPS	1.50	8 PC	12.00	✓
22 FRONT LH FENDER INNER SHIELD CLIP	1.50	6 PC	9.00	✓
23 BONNET	720.00	1 PC	720.00	✓
24 BONNET INNER TOP RUBBER	28.00	1 PC	28.00	X
25 BONNET LH HINGE	38.00	1 PC	38.00	X
26 FRONT BUMPER LH PARKING SENSOR	155.00	1 PC	155.00	✓
27 FRONT BUMPER PDC SENSOR WIRE HARNESS	210.00	1 PC	210.00	✓
28 HEADLAMP LH	800.00	1 PC	800.00	✓
29 HEADLAMP LH HID BULB	180.00	1 PC	180.00	✓
30 HEADLAMP LH CONTROL UNIT	330.00	1 PC	330.00	?
31 HEADLAMP LH COVER NO.1	50.00	1 PC	50.00	?
32 HEADLAMP LH BULB CORD	60.00	1 PC	60.00	?
33 FRT SUPPORT PANEL	530.00	1 PC	530.00	✓
34 FRONT SUPPORT PANEL INNER TOP GARNISH	140.00	1 PC	140.00	X
35 FRONT SUPPORT PANEL INNER TOP GARNISH CLIP	1.50	8 PC	12.00	✓
36 RADIATOR LH SIDE GARNISH	60.00	1 PC	60.00	?
37 BATTERY INSULATOR	80.00	1 PC	80.00	?

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : SOMPO INSURANCE SINGAPORE PTE LTD
 50 RAFFLES PLACE
 #05-01/06 SINGAPORE LAND TOWER
 SINGAPORE 048623
TEL: 64616555 **FAX:** 62213302
ATTN: Motor Claim Department
WS Ref: OD/SOMPO/AMK
Claim Type: Own Damage
Accident Date: 29/10/2022

Claim No: ES2291125
Estimate No: ES2291125/AMK
Date: 02 Nov 2022
Policy No: D22MTPV01008996
Veh Reg No: SNE7951S
Make/Model: LEXUS ES250
Chassis No: JTHBJ1GG002077985
Engine No: 2ARF002668
Reg. Date: 28/04/2015

Estimate Repair Cost to Vehicle No : SNE7951S

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
			6,109.00	
	Add 10%		610.90	6,719.90

Special Net

38 COOLANT	35.00	1 UNIT <i>na</i>	35.00	✓
39 FRONT NUMBER PLATE	35.00	1 PC <i>na</i>	35.00	✓
				70.00

Labour

40 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
41 REMOVE & REFIX FRT BUMPER & ATTACHMENTS,GRILLE,BONNET & ATTACHMENTS,HEADLAMPS,FRT LH FENDER;TO CUT,WELD & RENEW FRT SUPPORT PANEL;KNOCKING & REPAIR FRT LH CHASSIS FRAME & FRT LH FENDER INNER PANEL & REALIGN FRT LH DOOR THE SAME	900.00	1 LA	900.00	600
42 PUTTY & RESPRAY FRT BUMPER,REINFORCEMENT,PARKING SENSORS,BONNET & ATTACHMENTS,BONNET,FRT LH FENDER & INNER PANEL,FRT SUPPORT PANEL,FRT LH CHASSIS FRAME,FRT LH DOOR & ALL AFFECTED AREAS	800.00	1 LA	800.00	✓
43 REMOVE & REFIX FRT PARKING SENSORS WIRE HARNESS & RESET	80.00	1 LA	80.00	60
				1,880.00

Total S\$ 8,669.90

Add GST @ 7% 606.89

Total Amount payable S\$ 9,276.79

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	332F
Vehicle Details	
Vehicle No.:	SNE7951S
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS ES250 LUXURY AUTO
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2ARF002668
Chassis No.:	JTHBJ1GG002077985
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$39,966.00
Original Registration Date:	28 Apr 2015
First Registration Date:	28 Apr 2015
Transfer Count:	2
Actual ARF Paid:	\$47,953.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2025
PARF Rebate Amount:	\$28,771.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2025
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$78,001.00
COE Rebate Amount:	\$19,435.00
Total Rebate Amount:	\$48,206.00

The information contained herein is correct as at 31 Oct 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 31/10/2022 14:14 (SGT)
Reported by Both
Date of Accident 29/10/2022 14:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE TOWARDS TUAS
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SNE7951S

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner WANG CHUNLIANG
NRIC No SXXXX332F
Email Address PCL.CHUNLIANG@GMAIL.COM
Mobile Phone No (Phone) +65-84680816
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model LEXUS ES250 LUXURY AUTO
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 2494


INSURANCE COMPANY

Name of Insurance Company Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number D22MTPV01008996

DRIVER

Name of Driver WANG CHUNLIANG
NRIC No SXXXX332F
Date Of Birth 29/08/1983
Occupation Indoor

Date of accident: 29/10/2022 Time: 14:45 Location: PTE - towards Tuaru
My Vehicle A: SNE7951S Vehicle B: SHA312A Vehicle C: _____
SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police report No. T/2022 (029/2022)

Type: Own Damage claim

☒ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remainder: Please forward a copy of my efile accident report to:

My workshop :
Email address :
& myself :
Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: