

(08/11/13) wef

ASS. REC. BY:

REF:

CS3/SMR 22010971/Rqy3

4684

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBT 3185B

at Workshop m/s

ENG SOON PAINTING

of

YPR REG 3933 WOODLAND RD

Insured:

SMR

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

17K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBT 3185B

Yr Regn:

2022 / JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA NMAX 155 ABCVT c.c 155

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

23998

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH 3SG 5680 MK100927

Gen. Cond: Good / (Fail) / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110/70-13

R:

130/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

IRC

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

29/10/22

D.O.I.

07/11/22

Survey held at

ENG SOON

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☒ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 8K.

ESTIMATE RANGE OF REPAIR / NO. OF DAYS - 5K - 6K / 5 days

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

___ S + RS ___ SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	468H
Vehicle No.:	FBT3185B
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Nov 2022
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX 155 ABS CVT
Primary Colour:	Black
Manufacturing Year:	2021
Engine No.:	G3L8E0736925
Chassis No.:	MH35G5680MK100927
Maximum Power Output:	-
Open Market Value:	\$2,935.00
Original Registration Date:	18 Jan 2022
First Registration Date:	18 Jan 2022
Transfer Count:	1
Actual ARF Paid:	\$441.00

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

COE Expiry Date:	17 Jan 2032
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$9,381.00
COE Rebate Amount:	\$8,604.00
Total Rebate Amount:	\$8,604.00

The information contained herein is correct as at 15 Nov 2022

OK

Yamaha Nmax 155

Listing Type

Paid Ad

Brand

Yamaha

Model

Yamaha Nmax 155

Engine Capacity

155cc

Classification

Class 2B

Registration Date

20/04/2022

COE Expiry Date

19/04/2032

(9yrs 5mths 4days COE left)

Mileage

-

No. of owners

-

Type of Vehicle

Scooters

SGD **\$17500**